
Dixon-Vaca #1 007/177 -007/167





02/17/2012 Opera_.onControlTicket vers. 1 JLD9

SETC

Order

41620565

DSEX NMAT PRC

PATR/INSP 60066 DIXON-VACA #1+

Order type

T180 EL TRANS EXPENSE RECURRING

Status

REL

User Status

UNSC

Start date End date

03/01/2012 03/31/2012

FunctLocation 5 8 1

ETL.6730.POLE.WOOD

Equipment

40581862

60066 DIXON-VACA #1+-WOOD POLE 005/133 SINGLE WOOD POLE

MaintPlanGroup

TLP

ECES

MainWrkCenter

SACTO

ECES Sacramento

E - Schd Compl Yr 0

MaintenancePlan MaintPlanItem Revision No.

Partner

VLC5

JO

Address

Priority

Conerly-Scott

Veronica L.

Phone

916/760-3344

Class

ETLEQP

Electric Transmission Line Equipment TRI POST

002

12345

ETL FRAMINGCONFIG

ETL UNDERBUILT

LATITUDE

LONGITUDE

38.418975000000

-121.848324000000

Class

ETL POLE

ETL-POLE TRI POST

002

ETL FRAMINGCONFIG ETL UNDERBUILT

YES

YES

LATITUDE LONGITUDE

38.418975000000 -121.848324000000

Operation Work center

0004 ET TMAN1

ECES

Transmission OH Detailed Inspection

ELECTRIC TROUBLEMAN TRANSMISSION

Control key

INDT ETL03 CompConf No.

16309083

Operation key

MIN

Milestone

Work Duration 12

Activity type

MO

EarlStartDate

30

DAY

Number

1.

LateEndDate

03/01/2012 03/31/2012

Start time End time

00:00:00 00:00:00

Actual work

0

MIN

Total buffer

0

DOPER # OF NEW TAGS GENERATED BY OCR:

SIGNATURE OF SUPERI



DATE

Transmission Line Inspection Datasheet

Inspector Name: COOPER Date Inspection Completed: 3-29-12

Miles Inspected: 16 m; # Structures Inspected: 392

Plan Group : 41620565

Oper Volt

PATR/INSP 60066 DIXON-VACA #1+ ET Poles

ETT.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE Line Miles : 16 M

Work Center

: BFZ : ET_TMAN1 Detailed Ground Inspections

ELECTRIC TROUBLEMAN TRANSMISSION

Medium Impact

Struct Order: 392

Line Last Inspected : 41611823 REAS- DIXON-VACA #1 A9/132 RPR ACCESS GA (Reassess Tags Etrans)

Inspection Findings Data

					5-15-12 1/42 Swood CHOT 2 YEAR KOTTEN X ARM	CHIO 2 YEARS TRIPIN -	TYEAK	CA HER CHO	1 A9/230 Swo7 MCOZ I YEAR BROKEN BOND WIR	MC10 1 YEAR	O CHIO	I HOW MC10 I YEAR	CHOY CHOY	Swal CHO7	Date Found Structure Object Damage Priority Comments
		-		\vdash								_			H H H G G C
						227	7.5.V	大 _* ン	(2)	Z 0	No	>3h	455	Yes	Clearance Yes/No/Hot
					1059999990	165999889	88899801	105999886	105999885	188999301	105999883	288999301	188666501	106007910	Notification #

Supervisor's Initials:

Date Reviewed:

Transmission Line Inspection Datasheet

Inspector Name: COPER Date Inspection Completed: 3-29-12

Miles Inspected: 342 # Structures Inspected : 342

Wiles Inspected:

Oper Volt Plan Group Funct Loc 60 KV ETE. 6730. POLE. WOOD 60066 DIXON-VACA #1+-WOOD POLE PATR/INSP 60066 DIXON-VACA #1+ ET Poles

41620565

Line Miles : 16 M

Work Center

: BFZ ET_TMAN1

ELECTRIC TROUBLEMAN TRANSMISSION Detailed Ground Inspections Medium Impact

Struct Order: 392

Line Last Inspected : 41611823 REAS- DIXON-VACA #1 A9/132 RPR ACCESS GA (Reassess Tags Etrans)

Inspection Findings Data Date Found |Structure | Object 3-23-12 2-14-12 10/237 | Damage | Priority | Comments OMPLETED MINOR MORK CLEARED TREES OFF POLE & GUYS Dus out Switch Platform Est | Clearance Yes/No/Hot Notification

Supervisor's Initials:

Date Reviewed:

Inspector Name : COOPER Date Inspected : _

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	<u> </u>
Lat:		
Long:		
000/001 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40599369	[]completed/new finding(s)	
TRI PIN ARM DEAD END		
MEDIUM EQP (AERIAL LIFT; LINE TR		PG CONN'S ON SUMPERS TECH ID = 8/178 N SUB H Charto Krees OFF Pole & Guys
	Notes: '02 Survey: C015509	TECH TO - 0/170
38.401074000000	ACCESS AT VACA-DIVO	N SID - 0
-121.9180960000	I POSSO III VACA DIAO.	" There of these ace Pole - Line
000/002 SINGLE WOOD POLE	recompleted/no problems	Total # of Attachments:
40670096	[]completed/new finding(s)	
FLAT PIN ARM	[]pre-existing cond chked	
MEDIUM EQP (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
· · · · · · · · · · · · · · · · · · ·	Notes: '02 Survey: C015608	
38.401678000000	-	AZ GERM
-121.9173970000	ACCESS AT VACA-DIXO	8U8 //
000/003 LATTICE STEEL TOWER	Completed/second	0-1-7
40654173	completed/no problems	Total # of Attachments: 1
DOUBLE DEAD END ANGLE	[]completed/new finding(s)	CELL-UNKNOWN 1
MEDIUM EQP(AERIAL LIFT;LINE TR	[]pre-existing cond chked	2 as
PEDION EQF (AERIAL LIFT; LINE TR	[]not inspetd this patrol	
38.402687000000	Notes: '02 Survey: C015607	HOST FOR 6740 2 CELL SITES
	OFF MERIDIAN THOUGH	THE POLE YARD S/SUB
-121.9163250000		
000/004 LATTICE STEEL TOWER		Total # of Attachments:
40576443	[]completed/new finding(s)	
SUSP. STEEL DOUBLE CIR.	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015606	HOST FOR 6740
38.402628000000	İ	
-121.9132250000		
000/005 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40756286	frompleted/new finding(s)	DIST-0310456 1 X Flasher Irsul Corpard * Leaning hun Stub. South &
IRI PIN ARM DEAD END	More-existing cond chked	1 1 MAD MED TORUT COSDEND
	[]not inspctd this patrol	I Laguius hun stuh , South of
	Notes: '02 Survey: C015605	7
38.402611000000		
-121.9116610000	[
000/006 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
10756193	[]completed/new finding(s) [
RI PIN ARM	[]pre-existing cond chked	······································
	[]not inspctd this patrol	
	Notes: '02 Survey: C015604	
8.402560000000		
121.9109350000		
00/007 SINGLE WOOD POLE	completed/no problems i	Potral # of This characters at
0814340	[]completed/new finding(s) [Otal # of Attachments: 1
PT PIN ARM T N/C	[]pre-existing cond chked	\rightart - \righ
(- (- · · · ·	[]not inspetd this patrol	
,	Notes: '02 Survey: C015603	
3.40254000000	Acces: -02 Survey; C015603	
121.9101840000		·
00/008 SINGLE WOOD POLE	(loom) ored (e.	
	[]completed/no problems T	otal # of Attachments: 1
RI PIN ARM	completed/new finding(s) D	,
TAMENTAL .	[]pre-existing cond chked []not inspetd this patrol	* Broken Tie wine
	i idor inspeta this matrol (41 (1)1040=0 112 W1VLE
	Notes: '02 Survey: C015602	
402552000000 .21.9094610000		

Page 2

Inspector Name : COOPER Date Inspected : 2-14-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Interest Type, Owner Histed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
000/009 SINGLE WOOD POLE		Total # of Attachments: 1
40875444	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
!	Notes: '02 Survey: C015601	
38.402550000000		*
-121.9086950000		
000/010 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40865456 TRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.402536000000	Notes: '02 Survey: C015600 MONITOR TWISTED XAR	
-121.908000000	MUNITUR TWISTED XAR	rı
000/011 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40612500 SV(NK)	[]completed/new finding(s)	DIST-0310456 1
ANGLE 0-30 DEGREES	[]pre-existing cond chked	**********************************
	[]not inspetd this patrol	
	Notes: '02 Survey: C015599	
38.402564000000		
-121.9073370000		
000/012 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40589586	[\completed/new finding(s)	
TRI PIN ARM DEAD END	[]pre-existing cond chked	•
	[]not inspctd this patrol	
30 40044000000	Notes: '02 Survey: C015598	
38.402448000000 -121.9068350000		
000/013 SINGLE WOOD POLE	completed/no problems	
40695427 SV (NIC)	[]completed/no problems	Total # of Attachments:
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
33 220022	[]not inspetd this patrol	
	Notes: '02 Survey: C015597	
38.402168000000		
-121.9060440000		
000/014 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665431	[]completed/new finding(s)	*
T-(N/c)	[]pre-existing cond chked	
, C , y = 0	[]not inspetd this patrol	
20 402151000000	Notes: '02 Survey: C015596	
38.402151000000		
-121.9053110000 000/015 SINGLE WOOD POLE	l gomploted/es	Market 1 16 - 6 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -
40768117	completed/no problems lampleted/new finding(s)	Total # of Attachments:
TRI POST T- (CH/C)	[]pre-existing cond chked	
(-(CM/C)	[]not inspetd this patrol	
	Notes: '02 Survey: C015595	
38.402139000000		1
-121.9046210000		į.
000/016 SINGLE WOOD POLE		Total # of Attachments:
	[]completed/new finding(s)	John Garmaran D.
40767432 TRIANGLE-DOST 78	[]pre-existing cond chked	
-	[]not inspetd this patrol	
	Notes: '02 Survey: C015594	
38.402131000000		
-121.9039190000		

Page 3

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Inspector Name : 600PER

Date Inspected : 2-14-12

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		-15-0, 0,0000 220000
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
000/017 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40814342	[]completed/new finding(s	
ANGLE 0-30 DEGREES (-\(c)	[]pre-existing cond chked	
, , ,	[]not inspctd this patrol	
	Notes: '02 Survey: C015593	
38.402167000000		
-121.9031910000		
000/018 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40589587	completed/new finding(s)	
TRI PIN ARM DEAD END	[]pre-existing cond chked	D1 : 11/2 8- 2
	[]not inspctd this patrol	Pole is N/g PER OSMOSE 2008 INSPECT
	Notes: '02 Survey: C015592	700 403 400
38.402418000000		
-121.9022720000		
000/019 SINGLE WOOD POLE	[completed/no problems	Total # of Attachments: 1
40695277 SV(c) ANGLE 0-30 DEGREES	[]completed/new finding(s)	DIST-0310456 1
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015591	
38.402488000000		
-121.9016890000		
000/020 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40665479	[]completed/new finding(s)	DIST-0310456 1
T-1 (NC)	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.40250000000	Notes: '02 Survey: C015590	
-121.9009220000		
000/021 SINGLE WOOD POLE	completed/no problems	·
40756288	[completed/no problems [completed/new finding(s)	Total # of Attachments: 1
	[]pre-existing cond chked	DIST-0310456 1
************************************	[] not inspetd this patrol	
r	Notes: '02 Survey: C015589	
38.402454000000	Notes: .02 Survey: C015589	
-121.9001790000		
000/022 SINGLE WOOD POLE	//icompleted/no problems	The table 4 of the land
10767434	Completed/new finding(s)	Total # of Attachments: 1
FRI PIN ARM (-((p/c)		D191-0310496 J
····· (-(6/0)		·
ŕ	Notes: '02 Survey: C015588	
88.402464000000	02 Barvey: C015588	
121.8994480000		
000/023 SINGLE WOOD POLE		Total # of Attachmonts
10825143	[]completed/new finding(s)	Total # of Attachments: 1
RI PIN ARM DEAD FAND	[]pre-existing cond chked	270. 02.70.420 T
	[]not inspetd this patrol	
	Notes: '02 Survey: C015587	
		,
8.402490000000	,	
		1
8.402490000000 121.8987120000 00/024 SINGLE WOOD POLE	X]completed/no problems	Total # of Attachments: 1
		Total # of Attachments: 1
121.8987120000 00/024 SINGLE WOOD POLE	[]completed/new finding(s)	Total # of Attachments: 1 DIST-0310456 1
121.8987120000 00/024 SINGLE WOOD POLE 0813538	[]completed/new finding(s) []pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1
121.8987120000 00/024 SINGLE WOOD POLE 0813538	[]completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
121.8987120000 00/024 SINGLE WOOD POLE 0813538	[]completed/new finding(s) []pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1 "C 4 (rass

Page 4

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Inspector Name : COOPER

Date Inspected : 2-14-12

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config	İ	
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
001/025 SINGLE WOOD POLE	Sompleted/no problems	Total # of Attachments: 1
40865994 SV (NC)	[]completed/new finding(s)	DIST-0310456 1
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspctd this patrol	,
	Notes: '02 Survey: C015585	
38.402505000000		
-121.8972800000		
001/026 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40874335 SV (V/c)	[]completed/new finding(s)	DIST-0310456 1
ANGLE 0-30 DEGREES	[]pre-existing cond chked	
	[]not inspetd this patrol	
39 403221000000	Notes: '02 Survey: C015584	
38.402231000000		
-121.8966410000 001/027 SINGLE WOOD POLE		
40596147	completed/no problems	Total # of Attachments: 1
IRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
AND ELIV PRO	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.402255000000	Notes: '02 Survey: C015583	
-121.8958140000		
001/028 SINGLE WOOD POLE	971	
:0599330 / ODB POLE	completed/no problems	Total # of Attachments: 1
RI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
INI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.402257000000	Notes: '02 Survey: C015582	
121.8950880000		
001/029 SINGLE WOOD POLE	//completed/no problems	
10670100	[]completed/new finding(s)	Total # of Attachments: 1
TRI PIN ARM	[]pre-existing cond chked	DISI-0310456 I
	[] not inspetd this patrol	
	Notes: '02 Survey: C015581	Aug.
8.402254000000	01 241 toy: 2015501	
121.8942370000		
01/030 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0665481	[] completed/new finding(s)	DIST-0370456 1
RIANGER POST 70 (C)	[]pre-existing cond chked	
• • • •	[] not inspetd this patrol	
	Notes: '02 Survey: C015580	
8.402239000000		
121.8935220000		
01/031 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
0756290	[DIST-0310456 1
RI PIN ARM	[]pre-existing cond chked	· · · · · · · · · · · · · · · · · · ·
	[]not inspctd this patrol	
	Notes: '02 Survey: C015579	
3.402249000000	-	
121.8927510000		
1/032 SINGLE WOOD POLE		Total # of Attachments: 1
0767436	[]completed/new finding(s)	DIST-0310456 1
RI PIN ARM	[]pre-existing cond chked	,
	[]not inspctd this patrol	
	Notes: '02 Survey: C015578	
3.402246000000		

Page 5

Inspector Name : Cooper Date Inspected : 2-14-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		71-7
Access:		
HOST Tech ID/Equip #:	Notes	<u></u>
Lat:		
Long:		
001/033 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40814344	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
>	Notes: '02 Survey: C015577	
38.402239000000		
-121.8912530000		
001/034 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40823412	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015576	
38.402240000000		,
-121.8904640000		
001/035 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40865996	[]completed/new finding(s)	
TRI PIN ARM	pre-existing cond chked	
	[]not inspctd this patrol	"C" TRUSS INSTALLED.
7	Notes: '02 Survey: C015575	The li
38.402279000000		"C" TRUSS INSTALLED.
-121.8896890000		
001/036 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40865458	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 20 (H(c)	[]pre-existing cond chked	
-	[]not inspetd this patrol	
78 40000000000	Notes: '02 Survey: C015574	
38.40222300000	1	
-121.8889550000 001/037 SINGLE WOOD POLE		
40604091	. Completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 79 (-(VIC)	[]pre-existing cond chked	
• ,	[]not inspetd this patrol	
38,402219000000	Notes: '02 Survey: C015573	
-121.8881950000		
001/038 SINGLE WOOD POLE	[Ampleted/as a 13	
40599331	[completed/no problems] completed/new finding(s)	Total # of Attachments: 1
IRI PIN ARM	compressed/new rinding(s)	DIST-0310456 1
THE TAXABLE PROPERTY.	[]pre-existing cond chked	
	[]not inspctd this patrol Notes: '02 Survey: C015572	
38.402219000000	MONITOR VARM	Maine Mar "Oallan" and
-121.8874270000	PARTION ARRY	- Minor Rot, "Rolled" ours.
001/039 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
10670104	[]completed/new finding(s)	TOTAL # OI ALLACHMENTS:
TRI PIN ARM	[]pre-existing cond chked	
	[] not inspetd this patrol	j
	Notes: '02 Survey: C015571	
8.402212000000		
121.8867270000		Total # of Attachments:
	Trompleted/no problems	IOCAL # OL ACLICOMENES!
01/040 SINGLE WOOD POLE		
121.8867270000 001/040 SINGLE WOOD POLE 00695431 FRI PIN ARM	[]completed/new finding(s)	
001/040 SINGLE WOOD POLE 00695431	[]completed/new finding(s) []pre-existing cond chked	
01/040 SINGLE WOOD POLE 0695431	[]completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	
01/040 SINGLE WOOD POLE 0695431	[]completed/new finding(s) []pre-existing cond chked	

Inspector Name : Cooper

Date Inspected : 3-15-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #	
Equip #		Attachment Type/Owner Listed	
Framing Config		The state of the s	
Access:			
HOST Tech ID/Equip #:	Notes		
Lat:			
long:			
01/041 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:	
0665433	[]completed/new finding(s)	Total # Of Accadiments:	
RI PIN ARM	ore-existing cond chked	l.	
	[]not inspetd this patrol	XAM D.	
	Notes: '02 Survey: C015569	XAM RED-19R	
8.402242000000	100005: 02 Bulvey. C013303	•	1.1
121.8853260000			11
01/042 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:	
0756292	completed/new finding(s)		1
RI PIN ARM	[]pre-existing cond chked		
	[]not inspetd this patrol	MAKIN KTU	
	Notes: '02 Survey: C015568		
8.402226000000	MONITOR XARM		
121.8846420000) 3	also Has 16" Tours	
01/043 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:	
0612506	[]completed/new finding(s)		
RI PIN ARM	[]pre-existing cond chked		
	[] not inspetd this patrol	a contract of the contract of	
	Notes:		
3.402199000000	Noces.		
121.8839320000			
01/044 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1	
0767438	[] completed/new finding(s)	DIST 0330456 1	
RI PIN ARM	[]pre-existing cond chked	Dr21-0310429 T	1.1
	[] not inspctd this patrol		11
	Notes: '02 Survey: C015566		
3.402221000000	MONITOR XARM		11.
.21.8832720000	NOWITOR AREA		V
1/045 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1	
825137	[]completed/new finding(s)	DIST 03104EC 1	3-
I PIN ARM	[]pre-existing cond chked	D101-0310436 1	50
	[]not inspetd this patrol		
	Notes: '02 Survey: C015565		
.402208000000	of barvey. corssos		
21.8825750000	1 -		1
1/046 SINGLE WOOD POLE	Teompleted/no problems	Total # of Attachments: 1	
813540	[]completed/new finding(s)	DIST-0310456 1	
I PIN ARM	[]pre-existing cond chked	<u>~+○1.0010430 T</u>	11
	[] not inspetd this patrol		17
	Notes: '02 Survey: C015564		
.402214000000	January, 2013564		
21.8819010000			11
1/047 SINGLE WOOD POLE		Total # of Attachments: 1	
875401	[]completed/new finding(s)	DIST-0310456 1	11
I PIN ARM	[]pre-existing cond chked	UJIVIJU I	- 1/
	[]not inspetd this patrol		- 1/
	Notes: '02 Survey: C015563		
.402203000000			
21.8812240000			11 /
1/048 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments 1	//
365460	[]completed/new finding(s)	Total # of Attachments: 1	$\overline{}$
I PIN ARM	Pore-existing cond chked	DT91-03TA42P T	Л
	[] not inspctd this patrol	× 0 000 10 100	A
	Notes: 102 Suprest: Colsico	HAS WOOD SOUL	/Ib
	LATOCOD. UZ BULVEV: CUIDANZ		1 10
402209000000	^		/ 1/1

Page 7

Inspector Name : COOPER

Date Inspected: 3-15-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	1	
Long:	,	
001/049 SINGLE WOOD POLE	[Xcompleted/no problems	Total # of Attachments: 1
40612503	[]completed/new finding(s)	DISTRIBUTE OF ACCOUNTED TO
TRI PIN ARM	[]pre-existing cond chked	DIST-0310456 T
	[]not inspetd this patrol	
38.402195000000	Notes: '02 Survey: C015561	
-121.8793960000		
001/050 SINGLE WOOD POLE		
40589589	completed/no problems	Total # of Attachments:
/	(] completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	' y
	[]not inspctd this patrol	
	Notes: '02 Survey: C015560	
38.402209000000		
-121.8787730000		
001/051 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40695281	[]completed/new finding(s)	DIST-0310456 1
DOUBLE VERTICAL → € (N/c)	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015559	
38.402197000000		
-121.8782070000		
001/052 SINGLE WOOD POLE	recompleted/no problems	Total # of Attachments: 1
40654176	[]completed/new finding(s)	DIST 0310456 t
TRI PIN ARM	[]pre-existing cond chked	DT91-02T0420 T
	_	
	[]not inspetd this patrol	
78 40167100000	Notes: '02 Survey: C015558	
38.401671000000 -121.8782060000		
002/053 SINGLE WOOD POLE		Total # of Attachments: 1
10768090 3HPH TUANY (NC)	[]completed/new finding(s)	DIST-0310456 1
ERT PEN ARM DEAD END	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015557	
88.401175000000		
121.8781850000		
002/054 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
0756195	[]completed/new finding(s)	DIST-0310456 1
RI PIN ARM	inre-existing cond chked	
2	[]not inspetd this patrol	XAM KUZN. AYNS
	Notes: '02 Survey: C015556	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
8.400531000000		
121.8781770000		
02/055 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
0814346	[]completed/new finding(s)	DIST_0210456 1
RI PIN ARM	[]pre-existing cond chked	PTOI-0310430 T
2008	[]not inspctd this patrol	
ļ	Notes: '02 Survey: C015555	
8.399923000000	Notes: '02 Survey: C015555	
121.8781880000		
02/056 SINGLE WOOD POLE	mpleted/no problems	Total # of Attachments: 1
0823414	[]completed/new finding(s)	DIST-0310456 1
RI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015554	
3.399307000000	15 (a) (b) (a) (b) (a) (b) (b) (b) (b) (b) (b) (b) (b) (b) (b	
121.8781810000		

Page 8

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Inspector Name : Cooper

Date Inspected : 3-15-12

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Megacument type/Owner Pisted
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
002/057 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40865997	[]completed/new finding(s)	DISTRIBUTION OF ACCOMMENTS: 1
THE PEN ARM	[]pre-existing cond chked	DISI-0310456 I
1	[] not inspctd this patrol	
	Notes: '02 Survey: C015553	
38.398718000000	Notes. 102 Survey: C015553	
-121.8781740000	The state of the s	
002/058 SINGLE WOOD POLE	Completed/no problems	Imphal Hard and
40874337	[]completed/new finding(s)	Total # of Attachments: 1
TRI PIN ARM	[]pre-existing cond chked	DIST-0310456 1
1111 11111	[] not inspctd this patrol	
i		
38.398119000000	Notes: '02 Survey: C015552	
-121.8781590000		
002/059 SINGLE WOOD POLE	L. Marrietted	
40604094	completed/no problems	Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
IKI PIN ARM	[]pre-existing cond chked	
4	[]not inspctd this patrol	
38.397494000000	Notes: '02 Survey: C015551	
-121.8781330000		
002/060 SINGLE WOOD POLE	1	
40599371	recompleted/no problems	Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
IRI PIN ARM -	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.396929000000	Notes: '02 Survey: C015550	
-121.8781300000		
002/061 SINGLE WOOD POLE		
40670108	I loompleted/no problems	Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
INI I IIV MIII •	[]pre-existing cond chked []not inspctd this patrol	
38.396318000000	Notes: '02 Survey: C015549	
-121.8781470000		
002/062 SINGLE WOOD POLE	/ [Agampleted/==	
40665435	completed/no problems	Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
ween The Aids	[]pre-existing cond chked	
	[]not inspetd this patrol	
38.395680000000	Notes: '02 Survey: C015548	
-121.8781200000		
002/063 SINGLE WOOD POLE	completed/no problems	mah-1 // 6 200
40756294	[]completed/new finding(s)	Total # of Attachments: 1
	[]pre-existing cond chked	T 9440107107107
THE DIN AND THE	[]not inspetd this patrol	
	Notes: '02 Survey: C015547	
38.394946000000	102 Survey: C015547	
-121.8781080000		
002/064 SINGLE WOOD POLE	Teompleted/no problems	Total H of Therein
40767440	[]completed/new finding(s)	Total # of Attachments:
TRI PIN ARM	[]pre-existing cond chked	
7.12	[] not inspetd this patrol	
	Notes: '02 Survey: C015546	
38.394486000000		
-121.8781000000		

Page 9

Inspector Name : COOPER Date Inspected: 3-15-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	110000	
Long:		
002/065 SINGLE WOOD POLE	//lcompleted/no problems	
40825092		Total # of Attachments:
	[]completed/new finding(s)	
THE PLN ARM T-1 (UIC)	[]pre-existing cond chked	
1	[]not inspctd this patrol	
	Notes: '02 Survey: C015545	
38.393876000000	İ	
-121.8780860000		
002/066 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40813542	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]mot inspetd this patrol	
	Notes: '02 Survey: C015544	· · · · · · · · · · · · · · · · · · ·
38.393280000000		
-121.8780890000		
002/067 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40589590	[]completed/new finding(s)	10341 " OI ACCACIMENCS:
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
38.392710000000	Notes: '02 Survey: C015543	
	1	
-121.8780230000		
002/068 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40695285	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015542	
38.392101000000		
-121.8780610000		¥
002/069 SINGLE WOOD POLE	//completed/no problems	Total # of Attachments:
40654177	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015541	
38.391506000000	MONITOR XARM AND BRA	OTH
-121.8780300000	PROTEIN MARKY MID BRA	ACES .
002/070 SINGLE WOOD POLE	Completed/no problems	mohoù H = 5 avis d'
40768092 /		Total # of Attachments:
TRI PIN ARM	[\text{\text{\text{completed/new finding(s)}}}	
E TEA ERION	[]pre-existing cond chked	1
	[]not inspetd this patrol	
75. 222222222	Notes: '02 Survey: C015540	
38.39090000000		
-121.8780100000		
002/071 SINGLE WOOD POLE		Total # of Attachments:
10767498	[Acompleted/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	İ
	[]not inspetd this patrol	
	Notes: '02 Survey: C015539	
8.390287000000]	l
121.8780020000		
02/072 SINGLE WOOD POLE	/ completed/no problems /	Total # of Attachments: 1
0825145	[]completed/new finding(s)	DIST_02104E5 1
TRI PIN ARM	[]pre-existing cond chked	PTDI 0317430 T
	[]not inspetd this patrol	
8.389824000000	Notes: '02 Survey: C015538	
	I	
121.8780060000		ı

Page 10

Inspector Name : ____Coop-c__ Date Inspected: <u>3-21-12</u>

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Medium Impact

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Desc of Tech ID	Inspection Result	Attachments #	
Equip #		Attachment Type/Owner Listed	:
Framing Config			- 1
Access:			
HOST Tech ID/Equip #:	Notes		
Lat:	1.0000		7
Long:			
002/073 SINGLE WOOD POLE	1-1-1		- }
40823416	// rcompleted/no problems	Total # of Attachments: 1	\neg
TRIANGLE POST 20 (1)(C)	[]completed/new finding(s)	DIST-0310456 1	10
TRIANGLE POST	[]pre-existing cond chked		- 1
• -	[]not inspetd this patrol		
	Notes: '02 Survey: C015537		
38.389067000000	. *		
-121.8779950000			1
002/074 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1	-1
40865999	[]completed/new finding(s)	DIST-0310456 1	
TRI PIN ARM 🗸	[]pre-existing cond chked		- 1
	[]not inspetd this patrol		
	Notes: '02 Survey: C015536		
38.388442000000		11.011	
-121.8779930000	1. Yoke Ha	45 "C" /russ	
002/075 SINGLE WOOD POLE		Total # of Attachments: 1	[
10874339	[]completed/new finding(s)	DICT 0310456 1	\exists
TRIANGLE POST 70 / (4)C)	[]pre-existing cond chked	7277-03TA\$20 T	- 11
	-		- 11
•	[]not inspctd this patrol		- 11
88.38784600000	Notes: '02 Survey: C015535		71
		•	- 11
121.8780060000			- 11
002/076 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1	-11
.0612561		The state of the s	
	[]completed/new finding(s)	DIST-0310456 1	Ш
THE POST OF HC	[]completed/new finding(s) [pse-existing cond chked]	DIST-0310456 1	\parallel
	[]completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	DIST-0310456 1	$\ $
RIANGLE FOST 20(H(C)	[]completed/new finding(s) [pse-existing cond chked]	Pole Replace - IVA. LD TSP.	$\left\ \cdot \right\ $
8.387166000000	[]completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	DIST-0310456 1	\
8.387166000000 121.8778960000	[]completed/new finding(s) pre-existing cond chked []not inspetd this patrol Notes: '02 Survey: C015534	DIST-0310456 1	
8.387166000000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534	Pole Replace - ILL. LD TSP. Total # of attachments.	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534	Pole Replace - ILL. LD TSP. Total # of attachments.	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534	Pole Replace - ILL. LD TSP. Total # of attachments.	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534	Pole Replace - ILL. LD TSP. Total # of attachments.	-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534	Pole Replace - 142. LDTSP.	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Pole Replace - ILL. LD TSP. Total # of attachments.	\ -
8.387166000000 121.8778960000 02/077 SINGLE WOOD POLE SW 59 0589592 IELD SWITCH STRUCTURE	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Pole Replace - ILL. LD TSP. Total # of attachments.	\ - - -
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes:	Pole Replace - IVA. LD TSP Pole Replace - IVA. LD TSP Total # of Attachments: * Replace Switch Arm is R-N. * Clean Vegetation	 -
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems	Pola Replace - ITA. LDTSP Pola Replace - ITA. LDTSP Total # of Attachments: * Replace Switch Arm is R-N. * Clean Vege tation Total # of Attachments: 1	\ - - -
8.387166000000 121.8778960000 02/077 SINGLE WOOD POLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (-(c) TPAD	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []not inspctd this patrol Notes: []completed/no problems []completed/no problems []completed/new finding(s)	Pola Replace - ITA. LDTSP Pola Replace - ITA. LDTSP Total # of Attachments: * Replace Switch Arm is R-N. * Clean Vege tation Total # of Attachments: 1	
8.387166000000 121.8778960000 02/077 SINGLE WOOD POLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (-(c) TPAD	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []not inspctd this patrol Notes: []completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked	Pola Replace - ITA. LDTSP Pola Replace - ITA. LDTSP Total # of Attachments: * Replace Switch Arm is R-N. * Clean Vege tation Total # of Attachments: 1	
8.387166000000 121.8778960000 02/077 SINGLE WOOD POLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (-(c) TPAD	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Pola Replace - ITA. LDTSP Pola Replace - ITA. LDTSP Total # of Attachments: * Replace Switch Arm is R-N. * Clean Vege tation Total # of Attachments: 1	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (-(G) TPAD	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []not inspctd this patrol Notes: []completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked	Pola Replace - ITA. LDTSP Pola Replace - ITA. LDTSP Total # of Attachments: * Replace Switch Arm is R-N. * Clean Vege tation Total # of Attachments: 1	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD FOLE 0657522	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol	Pola Replace - ITA. LDTSP Pola Replace - ITA. LDTSP Total # of Attachments: * Replace Switch Arm is R-N. * Clean Vege tation Total # of Attachments: 1	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (-(c) TPAD INE AND BUCK 8.385762000000 121.8778300000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (- (C) TPAD INE AND BUCK 9.385762000000 121.8778300000 03/079 SINGLE WOOD POLE	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []not inspctd this patrol Notes: completed/no problems []not inspctd this patrol Notes: completed/no problems []pre-existing cond chked []not inspctd this patrol Notes: completed/no problems []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (- (c) TPAD 3.385762000000 121.8778300000 03/079 SINGLE WOOD POLE	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 3.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (- (c) TPAD 1.385762000000 121.8778300000 121.8778300000 121.8778300000 121.8778300000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []not inspctd this patrol Notes: completed/no problems []not inspctd this patrol Notes: completed/no problems []pre-existing cond chked []not inspctd this patrol Notes: completed/no problems []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 TELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE O657522 (- (c) TPAD 0.385762000000 0.21.8778300000 03/079 SINGLE WOOD POLE	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/no problems []completed/no problems []lcompleted/no problems []lcompleted/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no cond chked	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD FOLE 0657522	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []not inspctd this patrol Notes: []completed/new finding(s) []not inspctd this patrol Notes: []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/no problems []completed/no problems []lompleted/no problems []lompleted/no problems []lompleted/no problems []lompleted/new finding(s) []pre-existing cond chked []not inspctd this patrol	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 TELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (-(c) TAD 10.385762000000 121.8778300000 03/079 SINGLE WOOD POLE 0695314 11 POST	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/no problems []completed/no problems []lcompleted/no problems []lcompleted/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no cond chked	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 3.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (-(c) TPAD 1.385762000000 121.8778300000 121.8778300000 13/079 SINGLE WOOD POLE 1695314 11 POST 1.386214000000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []not inspctd this patrol Notes: []completed/new finding(s) []not inspctd this patrol Notes: []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/no problems []completed/no problems []lompleted/no problems []lompleted/no problems []lompleted/no problems []lompleted/new finding(s) []pre-existing cond chked []not inspctd this patrol	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 03/078 SINGLE WOOD POLE 0657522 T—(C), TYAD 1.385762000000 03/079 SINGLE WOOD POLE 0695314 01 POST 1.386214000000 021.8774070000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems completed/new finding(s) []not inspctd this patrol Notes: []completed/no problems []loompleted/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/no problems []completed/no problems []loompleted/no problems []loompleted/no problems []loompleted/no problems []loompleted/no problems []loompleted/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531	Pola Replace - Inn. IS Spotters. Total # of Attachments: ** Replace Switch Arm is Ren. **Clean Vegetation* Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD FOLE 0657522 (-(G) TYAD 3.385762000000 121.8778300000 03/079 SINGLE WOOD FOLE 0695314 RI POST 1.386214000000 121.8774070000 3/080 SINGLE WOOD FOLE SW 37	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531	Pole Replace - ITA. LATTED. Total # of Attachments: ** Replace Switch Arm is Ren. ** Clean Vegetation Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 10657522 (-(C) TPAD 1078 AND BUCK 10.385762000000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531 []completed/no problems []comp	Pola Replace - Inn. IS Spotters. Total # of Attachments: ** Replace Switch Arm is Ren. **Clean Vegetation* Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD FOLE 0657522 (-(G) TYAD 3.385762000000 121.8778300000 03/079 SINGLE WOOD FOLE 0695314 RI POST 1.386214000000 121.8774070000 3/080 SINGLE WOOD FOLE SW 37	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems completed/new finding(s) []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531 []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531	Pola Replace - Inn. IS Spotters. Total # of Attachments: ** Replace Switch Arm is Ren. **Clean Vegetation* Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 10657522 (-(C) TPAD 1078 AND BUCK 10.385762000000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems completed/new finding(s) pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531 []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []not inspctd this patrol	Pola Replace - Inn. IS Spotters. Total # of Attachments: ** Replace Switch Arm is Ren. **Clean Vegetation* Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD POLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 0657522 (-(c)) TPAD INE AND BUCK 9.385762000000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems completed/new finding(s) []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531 []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531	Pola Replace - Inn. IS Spotters. Total # of Attachments: ** Replace Switch Arm is Ren. **Clean Vegetation* Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1	3-
8.387166000000 121.8778960000 02/077 SINGLE WOOD FOLE SW 59 0589592 IELD SWITCH STRUCTURE 8.386637000000 121.8778700000 03/078 SINGLE WOOD POLE 10657522 (-(C) TPAD 1078 AND BUCK 10.385762000000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000 121.8778300000	[]completed/new finding(s) []pse-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015534 []completed/no problems completed/new finding(s) pre-existing cond chked []not inspctd this patrol Notes: []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015532 []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015531 []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []completed/no problems []not inspctd this patrol	Pola Replace - Inn. IS Spotters. Total # of Attachments: ** Replace Switch Arm is Ren. **Clean Vegetation* Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1	3-

Page 11

Inspector Name : Cooper Date Inspected: 3-21-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	- 500 4	Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	į.	
Long:	. >	
003/081 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40601228	[]completed/new finding(s)	DIST-0310456 1
TOST (U)	[]pre-existing cond chked	
	[]not inspctd this patrol	
28 28828800000	Notes: '02 Survey: C015529	
38.387372000000 -121.8763700000		
003/082 SINGLE WOOD POLE	(2)	
40874379	lcompleted/no problems	Total # of Attachments: 1
TRI POST TAKE	[]completed/new finding(s)	DIST-0310456 1
1001 - (0)	[]pre-existing cond chked	
1	[]not inspctd this patrol Notes: '02 Survey: C015528	
38.388151000000	102 Survey: C015528	
-121.8757460000		· «
003/083 SINGLE WOOD POLE	/completed/no problems	Total # of Attachments: 1
40875438	[]completed/new finding(s)	DIST-0330466 1
CRI POST (C)	[]pre-existing cond chked	DEGT-03T0430 T
	[]not inspctd this patrol	
1	Notes: '02 Survey: C015527	
38.388890000000		(9)
-121.8750240000		
003/084 SINGLE WOOD POLE		Total # of Attachments: 1
40823445	[]completed/new finding(s)	DIST-0310456 1
THE BOST TU(C)	[]pre-existing cond chked	= -5-7
1 '\'	[]not inspctd this patrol	
1	Notes: '02 Survey: C015526	
38.389609000000		
-121.8743940000	<u> </u>	
003/085 SINGLE WOOD POLE 40825104	completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
T-1(c)	[]pre-existing cond chked	
1	[] not inspetd this patrol	
38.390212000000	Notes: '02 Survey: C015525	
-121.8738830000		ļ
003/086 SINGLE WOOD POLE	4completed/no problems	
40752054	[]completed/new finding(s)	Total # of Attachments: 1
TRI 1009 (c)	[]pre-existing cond chked	DIST-0310456 1
	[] not inspetd this patrol	ĺ
-	Notes: '02 Survey: C015524	
38.390847000000	02 Burvey: CO18524	
-121.8733270000	l. /	
003/087 SINGLE WOOD POLE		Total # of Attachments: 1
40751995	[]completed/new finding(s)	DIST-0310456 1
TRI POST T-((°)	[]pre-existing cond chked	
• • • • • • • • • • • • • • • • • • • •	[]not inspetd this patrol	
	Notes: '02 Survey: C015523	
38.391491000000		
-121.8727280000		ł
003/088 SINGLE WOOD POLE	* 1completed/no problems	Total # of Attachments: 1
40657521	[]completed/new finding(s)]	DIST-0310456 1
	[]pre-existing cond chked	
PRI POST (C)	- ,t	
TRE-POST 7-(C)	[]not inspetd this patrol	
38.392111000000 -121.8721820000	[]not inspetd this patrol	

Page 12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Inspector Name : COOPER

Date Inspected: 3-21-12

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		aggorgent labelowner HIRCEG
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	i	
Long:		
003/089 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40677723	[]completed/new finding(s)	DIST-0310456 1
TRI TOST T-(い)	[]pre-existing cond chked	7
, 6-3	[]not inspetd this patrol	
i	Notes: '02 Survey: C015521	
38.392619000000	1	
-121.8716850000		
003/090 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40599373	[]completed/new finding(s)	DIST-0310456 1
3 HORIZONTAL POST DELTA	[]pre-existing cond chked	
3440(0)	[]not inspetd this patrol	
T	Notes: '02 Survey: C015520	<u> </u>
38.393172000000		
-121.8711650000		
003/091 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40816615	[]completed/new finding(s)	DIST-0310456 1
TRE POST (C)	[]pre-existing cond chked	
	[]not inspctd this patrol	
· ·	Notes: '02 Survey: C015519	
38.393932000000		
-121.8705190000		•
003/092 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40825102	[]completed/new finding(s)	DIST-0310456 1
TRI POST TIG	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015518	
38.394695000000		
-121.8698910000	()	
003/093 SINGLE WOOD POLE	X completed/no problems	Total # of Attachments: 1
40759643	[]completed/new finding(s)	DIST-0310456 1
TRL POST (C)	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015517	
38.395380000000		
-121.8692600000		
003/094 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40768100	[]completed/new finding(s)	DIST-0310456 1
POST (J(NC)	[]pre-existing cond chked	
· ·	[]not inspctd this patrol	
29 295155000000	Notes: '02 Survey: C015516	
38.396155000000		
121.8686120000		
003/095 SINGLE WOOD POLE 0657519	completed/no problems	Total # of Attachments: 1
	[] completed/new finding(s)	DIST-0310456 1
	[]pre-existing cond chked	
•	[]not inspetd this patrol	
8.396891000000	Notes: '02 Survey: C015515	
121.8679180000	,	
04/096 SINGLE WOOD POLE	X	
0695310		Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
TI POST (-1 (N/C)	[]pre-existing cond chked []not inspctd this patrol	
~ /	Notes: '02 Survey: C015514	
8.397669000000	100000. 02 Survey: C015514	
121.8672340000		
	1	

Page 13

Inspector Name : Cooper Date Inspected : 3

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	,	
004/097 SINGLE WOOD POLE		
40592607		Total # of Attachments: 1
TRI POST T-1(C)	[]completed/new finding(s)	DIST-0310456 1
T-(8)	[]pre-existing cond chked	
\ '	[]not inspctd this patrol	
22 222	Notes: '02 Survey: C015513	
38.398479000000		
-121.8664870000		
004/098 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40612514	[]completed/new finding(s)	DIST-0310456 1
T-1 (a)	[]pre-existing cond chked	
(0)	[]not inspctd this patrol	
	Notes: '02 Survey: C015512	
38.399158000000	_	
-121.8659270000		
004/099 SINGLE WOOD POLE	roompleted/no problems	Total # of Attachments: 1
40868327	[]completed/new finding(s)	DIST-0310456 1
TRI POST T-((c)	[]pre-existing cond chked	2701-03T0430 T
1-163	[] not inspetd this patrol	
	Notes: '02 Survey: C015511	
38.39989900000	Mocca. Uz Survey: CU15511	
-121.8652670000	1	
004/100 SINGLE WOOD POLE	ompleted/no problems	
40875407		Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
THE POST TIME (°)	[]pre-existing cond chked	
	[]not inspctd this patrol	
20 4005222222	Notes: '02 Survey: C015510	
38.400633000000		
-121.8646000000		
004/101 SINGLE WOOD POLE		Total # of Attachments: 1
40823451	[]completed/new finding(s)	DIST-0310456 1
TRI POST T-1(C)	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015509	
38.401405000000		
-121.8639110000		
004/102 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40825100	[]completed/new finding(s)]	DIST-0310456 1
FRI POST (- (C)	[]pre-existing cond chked	
- -	[]not inspctd this patrol	
	Notes: '02 Survey: C015508	
38.402165000000		1
-121.8632340000	EXECTS/ INSU	LATING SLIGHTLY "WINGEN"
004/103 SINGLE WOOD POLE		
10759641	[]completed/new finding(s) [Cotal # of Attachments: 1
TRI POST		71ST-0310456 1
	nre-existing cond chked	V-1 \
	[]not inspctd this patrol	KEPLACE ANCHON -NEED TO DO
8.402652000000	Notes: '02 Survey: C015507	
121.8628210000		
04/104 SINGLE WOOD POLE	completed/no problems T	Otal # of Attachments: 1
0751993	[]completed/new finding(s) r	DIST-0310456 1
RI POST DEAD END 60	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Makes 100 C	
	Notes: '02 Survey: C015506	
8.403296000000 121.8622070000	Notes: '02 Survey: C015506	

Page 14

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Inspector Name : ______

Date Inspected:

Detailed Ground Inspections

Desc of Tech ID Inspection Result Attachments # Equip # Attachment Type/Owner Listed Framing Config Access: HOST Tech ID/Equip #: Notes Lat: Long: | Teompleted/no problems | Total # of Atta | | completed/new finding(s) | DIST-0310456 1 004/105 SINGLE WOOD POLE Total # of Attachments: 1 40665492 TRI POST. (NC) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015505 38.403852000000 -121.8617400000 004/106 SINGLE WOOD POLE completed/no problems Total # of Attachments: 1 40695306 [] cmpleted/new finding(s) DIST-0310456 1 []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015504 38.404413000000 -121.8612560000 004/107 SINGLE WOOD POLE completed/no problems Total # of Attachments: 1 40592606 completed/new finding(s) DIST-0310456 1 []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015503 38.405015000000 -121.8607010000 004/108 SINGLE WOOD POLE completed/no problems Total # of Attachments: 1 40601225 []completed/new finding(s) DIST-0310456 1 T-1 (11/c) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015502 38.405641000000 -121.8601850000 004/109 SINGLE WOOD POLE Mccmpleted/no problems Total # of Attachments: 1 40862038 []completed/new finding(s) DIST-0310456 1 TRI POST DEAD END 60 []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015501 38.406254000000 -121.8596010000 004/110 SINGLE WOOD POLE | Completed/no problems | Total # of Atta | Completed/new finding(s) | DIST-0310456 1 Total # of Attachments: 1 [lpre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015500 38.406507000000 -121.8590040000 004/111 SINGLE WOOD POLE completed/no problems Total # of Attachments: 1 40816613 []completed/new finding(s) DIST-0310456 1 ANGLE 30-80 DEGREES []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015499 38.406762000000 -121.8583710000 004/112 SINGLE WOOD POLE completed/no problems Total # of Attachments: 1 40817730 []completed/new finding(s) DIST-03/10456 1 []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015498 38.407313000000 -121.8582910000

Page 15

Inspector Name : Cooper Date Inspected : 3-28-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #	
Equip #		Attachment Type/Owner Listed	3-21-
Framing Config		worsemment Tabelowner Trated	
Access:			
HOST Tech ID/Equip #:	Notes		1 1
Lat:	Noces		
Long:			
 .			1 1
004/113 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1	
40767492	[]completed/new finding(s	DIST-0310456 1	-1 I
PRI POST DEAD END 60	[]pre-existing cond chked		1 /
	[]not inspctd this patrol		- 1 I
	Notes: '02 Survey: C01549'		
38.407986000000	Noces. 02 Barvey: Colb49	I	1 1
-121.8580520000			
004/114 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1	
0768098	[]completed/new finding(s) DIST-0310456 1	1.1
RI POST	[]pre-existing cond chked		1 1
T-1(e)	[]not inspctd this patrol		1 1
- 1 -	Notes: '02 Survey: C015496		
88.408326000000	Jacob. 02 Bulvey: CO15498] [
121.857779000			i V
			_
04/115 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1	
:0665490	[completed/new finding(s)	DIST-0310456 1	3-29.
RI POST	[]pre-existing cond chked		I
1c>	[]not inspetd this patrol		
T-1 (0)	Notes: '02 Survey: C015495		\
8.408907000000	Modes: 02 Survey: C015495	,	
121.8573250000			
			1 1
05/116 SINGLE WOOD POLE	[completed/no problems	Total # of Attachments: 1	——————————————————————————————————————
0695301	[]completed/new finding(s)	DIST-0310456 1	1 1
PT POST	[]pre-existing cond chked		1 1
T-1(c)	[]not inspctd this patrol		1 /
. \	Notes: '02 Survey: C015494		1 /
8.409485000000	Notes: '02 Survey: C015494		
· ·			1 1
121.8567670000			
05/117 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1	
0592604	[]completed/new finding(s)	DIST-0310456 1	1 1
PT POST	[]pre-existing cond chked		1 1
<u> てー((゚)</u>	[]not inspetd this patrol		1 1
(- (()	Notes: '02 Survey: C015493	<u> </u>	1 1
3.410075000000	Noces: 102 Survey: C015493		
121.8563170000	1		1 1
			1 1
05/118 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1	
0612511	[completed/new finding(s)	DIST-0310456 1	
RI POST	[]pre-existing cond chked		
~ ~ (c)	[] not inspetd this patrol		1 1
. ,			1 1
4106777	Notes: '02 Survey: C015492		
.410652000000			1 1
21.8556850000			11
5/119 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1	
868325	[completed/new finding(s)		
LPOST - \ (.)	[]pre-existing cond chked	D121-0210436 T	1 1
T-((·)	I ipre-existing cond chied		1 1
•	[]not inspetd this patrol		l i
444.044.04	Notes: '02 Survey: C015491		
.411261000000			1 1
21.8551380000			
5/120 SINGLE WOOD FOLE	completed/no problems	Total # of Attachments: 1	/
875405	[]completed/new finding(s)	DICT 02104FC 3	11
		DT21_02T0#20 T	1.1
 POST	[]pre-existing cond chked		11
	[]not inspctd this patrol		1 1
			1 (
	Notes: '02 Survey: C015490		
.411858000000	Notes: '02 Survey: C015490		

Page 16

Inspector Name : ___Coopst Date Inspected: 3-28-12

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config	ľ	The state of the s
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
005/121 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40816611	[]completed/new finding(s)	DIST_0210456 1
TRI POST	[]pre-existing cond chked	MIBI-0310426 1
7-1 (0)	[] not inspetd this patrol	
(-(0)	Notes: '02 Survey: C015489	
38.412477000000	100003. 02 Bulvey: C015489	
-121.8540850000		
005/122 SINGLE WOOD POLE	Completed/no problems	
40825098	[]completed/new finding(s)	Total # of Attachments: 1
TD1 PART	[]pre-existing cond chked	DT21-0310429 T
て (()	[]not inspetd this patrol	
(()		
38.413013000000	Notes: '02 Survey: C015488	*
-121.8535680000		
005/123 SINGLE WOOD POLE	I d gorm I should be seen a should be	
40759639	completed/no problems	Total # of Attachments: 1
EDT DOGG	[]completed/new finding(s)	DIST-0310456 1
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	[]pre-existing cond chked	
()	[]not inspctd this patrol	
38 47360750000	Notes: '02 Survey: C015487	
38.413621500000		
-121.8530470000		
005/124 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40768096	[]completed/new finding(s)	DIST-0310456 1
T-1 (c)	[]pre-existing cond chked	
((()	[]not inspetd this patrol	
	Notes: '02 Survey: C015486	
38.41423000000	1	
-121.8525260000		
005/125 SINGLE WOOD POLE		Total # of Attachments: 1
40657517	[]completed/new finding(s)	DIST-0310456 1
ポー POST てー((c)	[]pre-existing cond chked	
(-((c)	[]not inspetd this patrol	
	Notes: '02 Survey: C015485	
38.414845000000		
-121.8520120000		
005/126 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
10695389	[completed/new finding(s)	DIST-0310456 1
T-1(c)	[]pre-existing cond chked	
((()	[]not inspetd this patrol	
	Notes: '02 Survey: C015484	
88.415434000000		
121.8514720000		
05/127 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
0592603	[completed/new finding(s)]	
REF POST てー(C)	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015483	
8.416024000000]	
121.8509490000	,,	
05/128 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0825096	[]completed/new finding(s)	DIST-0310456 1
RI POST T-16)	[]pre-existing cond chked	
(—(E)	[]not inspctd this patrol	
	INOTES: '02 Survey: C015492	
8.416632000000	Notes: '02 Survey: C015482	

Page 17

Inspector Name : Cooper Date Inspected: 3-20-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		TINC AMET TIREG
Access:		
HOST Tech ID/Equip #:	Notes	<u></u>
Lat:		
Long:		
005/129 SINGLE WOOD POLE	completed/no problems	
40759627	Completed/no problems	Total # of Attachments: 1
TRI 2051 T-1 (p/c)	[]completed/new finding(s)	DIST-0310456 1
1-1-1-1-1-1	[]pre-existing cond chked	
	[]not inspctd this patrol	
38.41688200000	Notes: '02 Survey: C015481	
-121.8501650000		
005/130 SINGLE WOOD POLE		
40759895	//completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
3 HORIZONTAL POST DELTA (VK)	[]pre-existing cond chked	1
<u> </u>	[]not inspctd this patrol	
	Notes: '02 Survey: C015480	
38.417218000000		
-121.8498220000		
005/131 SINGLE WOOD POLE	Alcompleted/no problems	Total # of Attachments: 1
40665436	[]completed/new finding(s)	DIST-0310456 1
TRI POST TIME (NE)	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015479	
38.417823000000	1 2 2 2 2 3 3 6 6 7 3 4 7 9	
-121.8493060000	1 .	
005/132 SINGLE WOOD POLE	completed/no problems	Total # of New Y
40695297	[]completed/new finding(s)	Total # of Attachments: 1
TEL TOURT TOUR (HK)	[]pre-existing cond chked	D15T-0310456 1
(-(())		
	[]not inspctd this patrol	
38.418428000000	Notes: '02 Survey: C015478	
-121.8488280000		
005/133 SINGLE WOOD POLE		
40581862	completed/no problems	Total # of Attachments: 1
THE POST TU	[]completed/new finding(s)	DIST-0310456 1
(-(00)	[]pre-existing cond chked	
-	[]not inspetd this patrol	
38.418975000000	Notes: '02 Survey: C015477	
	1	
-121.8483240000		
005/134 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
0601222	[] completed/new finding(s)	DIST-0310456 1
T-1 (VK)	[]pre-existing cond chked	
(-, (, -,	[] not inspetd this patrol	· ·
*	Notes: '02 Survey: C015476	
8.419612000000	1	
121.8477740000	l _	
05/135 SINGLE WOOD POLE	lcompleted/no problems	Total # of Attachments: 1
0874341	[]completed/new finding(s)	DIST-0310456 1
RE POST (NIC)	[]pre-existing cond chked	
` ``	[] not inspetd this patrol	
	Notes: '02 Survey: C015475	
8.420177000000	02 Burvey: C015475	
121.8472060000		
06/136 SINGLE WOOD POLE		
0875442	completed/no problems T	Total # of Attachments: 1
	[]completed/new finding(s) [DIST-0310456 1
T—((MC)	[]pre-existing cond chked	
• • •	[]not inspctd this patrol	
	Notes: '02 Survey: C015474	
3.420780000000		
121.8467060000		

Page 18

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Inspector Name : COOPER

Date Inspected: 3-20-17

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		I The state of the
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
006/137 SINGLE WOOD POLE	[completed/no problems	Total # of Attachments: 1
40809773	[]completed/new finding(s)	DIST-0310456 1
FRI POST T-L(NO)	[]pre-existing cond chked	*
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspctd this patrol	
	Notes: '02 Survey: C015473	
38.421367000000		
-121.8461680000	トノ	
006/138 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40825149	[]completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
TRI POST TIME (MG)	[]not inspetd this patrol	
	Notes: '02 Survey: C015472	
38.421969000000		
-121.8456790000	<u>C2</u>	
006/139 SINGLE WOOD FOLE	//completed/no problems	Total # of Attachments: 1
40759635	[]completed/new finding(s)	DIST-0310456 1
T-1 (Wo)	[]pre-existing cond chked	
(-1 (Mo)	[]not inspctd this patrol	
	Notes: '02 Survey: C015471	
38.422537000000		
-121.8451320000	Ω	
006/140 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40768094	[]completed/new finding(s)	DIST-0310456 1
TRI POST TU (N)	[]pre-existing cond chked	
• • /	[]not inspctd this patrol	
	Notes: '02 Survey: C015470	
38.423136000000		
-121.8445930000		
006/141 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
10665487 TRI POST TUN (416)	[]completed/new finding(s)	DIST-0310456 1
TRI POST TO (MIC)	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015469	
38.423730000000	1	
-121.8440870000		
006/142 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
10695385	[] completed/new finding(s)	DIST-0310456 1
THE FOST TUCKE	[]pre-existing cond chked	
V	[]not inspctd this patrol	
10 42420788000	Notes: '02 Survey: C015468	
38.424297000000		
121.8435910000	<u> </u>	
06/143 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
9586212	[]completed/new finding(s)	DIST-0310456 1
T 1 (116)	[]pre-existing cond chked	
T-1 (b1c)	[]not inspctd this patrol	
8.424904000000	Notes: '02 Survey: C015467	
8.424904000000 121.8430690000	le.	
06/144 SINGLE WOOD POLE	-X	
0868990		Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
INGLE VERTICAL DEAD END	[]pre-existing cond chked	,
()	[]not inspetd this patrol	
8.425254000000	Notes: '02 Survey: C015466	
121.8427550000		
121-042/330000		

Page 19

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Inspector Name : 3-26-12

Date Inspected : _

Inspection Result	Attachments #
	Attachment Type/Owner Listed
Notes	
Notes	
1	
<u> </u>	
[completed/no problems	Total # of Attachments: 1
[]completed/new finding(s)	DIST-0310456 1
[]pre-existing good chked	1010130 I
I had inspetd this patrol	
Webser top 5	
Notes: '02 Survey: C015465	
completed/no problems	Total # of Attachments: 1
[]completed/new finding(s)	DIST-0310456 1
02 Survey: C015464	
completed/no problems	Total # of Attachments: 1
[]completed/new finding(s)	DIST-0310456 1
[]pre-existing cond chked	
Moces: 02 Survey: Cuis463	
1	
<u> </u>	
	Total # of Attachments: 1
[]completed/new finding(s)	DIST-0310456 1
[]pre-existing cond chked	
[]not inspetd this patrol	
T Completed/no problems	Total # of Attachments: 1
[] completed/new finding(s)]	DIST-0310456 1
[]pre-existing cond chked	
[]not inspetd this patrol	
Notes: '02 Survey: C015461	
1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
(Carrel of 1/2	
	Total # of Attachments: 1
	DIST-0310456 1
[]pre-existing cond chked	
[]not inspetd this patrol	
VI complete d'anni	
Kicompieted/no problems T	Cotal # of Attachments: 1
	IST-0310456 1
[]not inspctd this patrol	
Notes: '02 Survey: C015459	
_	
Kloompleted/na natio	
	otal # of Attachments: 1
	IST-0310456 1
[]pre-existing cond chked	
[]not inspctd this patrol	
[]not inspctd this patrol	
	[]completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015464 Completed/no problems Jcompleted/new finding(s) Jpre-existing cond chked Jnot inspctd this patrol Notes: '02 Survey: C015463 Completed/new finding(s) Jpre-existing cond chked Jnot inspctd this patrol Notes: '02 Survey: C015462 Completed/new finding(s) Jpre-existing cond chked Jnot inspctd this patrol Notes: '02 Survey: C015461 Completed/new finding(s) Jpre-existing cond chked Jnot inspctd this patrol Notes: '02 Survey: C015461 Completed/new finding(s) Jpre-existing cond chked Jnot inspctd this patrol Notes: '02 Survey: C015460 Completed/new finding(s) Jpre-existing cond chked Jnot inspctd this patrol Notes: '02 Survey: C015450 Completed/new finding(s) Jpre-existing cond chked Jpre-existing

Page 20

Inspector Name : _ Date Inspected : _

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Framing Config Access: HOST Tech ID/Equip #: Lat: Long: 1006/133 SINMLE WOOD POLS 138.43055900000 121.8387840000 122.1387840000 123.837840000 124.8387840000 125.65/185 SINMLE WOOD POLE 1	Desc of Tech ID	Inspection Result	Attachments #
Notes Notes Notes Notes	Equip #		Attachment Type /Owner Tighed
NOTE Inches Inc	Framing Config		
Lat: Long	Access:		
Dong: Dong		Notes	
Decirity Property Decirity			
Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 I I I I I I I I I		/	
Completed/new finding(s) District Completed/new finding(s) District Completed/new finding(s) District Distr	006/153 SINGLE WOOD POLE	tompleted/no problems	Total # of Attachments: 1
### Pro-existing cond chied Inct inspetd this parts Notes: '02 Survey: C015497 Notes: '02 Survey:			
Inot imspect this petrol Notes: '02 Survey: C015457 Notes: '02 Survey: C015457 Notes: '02 Survey: C015457 Notes: '02 Survey: C015456 Notes: '02 Surve	TRI POST A A (NO)		i e e e e e e e e e e e e e e e e e e e
38.43055900000		[] not inspetd this patrol	REVIALE DOLE Fruis Comband
121.33978400000 122.3397840000 123.33978400000 123.33978400000 123.33978400000 123.33978400000 123.3397880000		Notes: '02 Survey: C015457	The state contractory
	38.430559000000		,
1 Name Nam			*
	The state of the s		
Total speed this parrol Notes: '02 Survey: CO15456			DIST-0310456 1
Netes: 102 Survey: COLSASE Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Completed/no proble	(1000)	[]pre-existing cond chked	
38.431231000000			
121. 8384830000 106/155 SINSLE WOOD FOLE 1 1 1 1 1 1 1 1 1	28 421221000000	Notes: '02 Survey: C015456	
Doe/1455 SINNLE WOOD FOLE All Does D			
	The rest of the contract of th		Total # of Attachments: 1
Int import this patrol Notes: '02 Survey: C015455 Notes: '02 Survey: C015455 Notes: '02 Survey: C015455 Notes: '02 Survey: C015455 Notes: '02 Survey: C015456 DIST-0310456 DIST-			DIST-0310456 1
Notes: '02 Survey: C015455 Notes: '02 Survey: C015455 Notes: '02 Survey: C015455 Notes: '02 Survey: C015455 Notes: '02 Survey: C015456 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015454 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015452 Notes: '02 Survey: C015452 Notes: '02 Survey: C015452 Notes: '02 Survey: C015452 Notes: '02 Survey: C015452 Notes: '02 Survey: C015452 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015452 Notes: '02 Survey: C015452 Notes: '02 Survey: C015452 Notes: '02 Survey: C015452 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015453 Notes: '02 Survey: C015450 Notes: '02 Sur	I HOMEZONIAN POST DELITA (NIC)		
38.431806000000 121.8378830000	,		
121,8376830000	38.431806000000	Notes: '02 Survey: C015455	
Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456		1	
1		[Magmalated/na much]	
		[] completed/no problems	Total # of Attachments: 1
Notes: 102 Survey: C015454		[] hre-existing cord shind	DIST-0310456 1
Notes: '02 Survey: C015454	(~ / M/C		
38.432442000000			
Completed/no problems Comp	38.432442000000	02 Barvey, Cors454	
Completed/no problems Comp	•		
1	007/157 SINGLE WOOD POLE	completed/no problems	Total # of Attachments 1
	40767442		DIST-0310456 1
I not inspect this patrol	TRE POST T- UIC		2101-0310430 1
Notes: '02 Survey: C015453 Notes: '02 Survey: C015453			
38.432993000000			
007/158 SINGLE WOOD FOLE 40759891 RI POST	38.432993000000		
I completed/new finding(s) I pre-existing cond chked I not inspetd this patrol Notes: '02 Survey: C015452			• 1
			Total # of Attachments: 1
[]pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015452 38.43361000000 007/159 SINGLE WOOD POLE 40665488 [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015451 38.434211000000 -121.8355800000 007/160 SINGLE WOOD FOLE 40695294 FRE FOST Notes: '02 Survey: C015450] pre-existing cond chked] not inspect dis patrol DIST-0310456 1 DIST-0310456 1 DIST-0310456 1 DIST-0310456 1 DIST-0310456 1] pre-existing cond chked] not inspect dhis patrol Notes: '02 Survey: C015450			DIST-0310456 1
Completed/no problems Total # of Attachments: 1	T-\ NL	[]pre-existing cond chked	
38.433604000000 -121.8361000000 007/159 SINGLE WOOD POLE 40665488 RM1 POST U	j , , , , , , , , , , , , , , , , , , ,		
-121.8361000000 007/159 SINGLE WOOD POLE 40665488 TWI FOST Completed/no problems Total # of Attachments: 1	<u> </u>	Notes: '02 Survey: C015452	
007/159 SINGLE WOOD POLE 40665488 [] completed/no problems [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015451 [] completed/no problems [] Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 Notes: '02 Survey: C015450 Notes: '02 Survey: C015450	38.433604000000		İ
Completed/new finding(s) DIST-0310456 1			
Total # of Attachments: 1 I pre-existing cond chked I not inspect this patrol	L		Total # of Attachments: 1
[] not inspect this patrol Notes: '02 Survey: C015451 38.434211000000 -121.8355800000 007/160 SINGLE WOOD FOLE 40695294 TRI POST Notes: '02 Survey: C015450 Total # of Attachments: 1 DIST-0310456 1 DIST-0310456 1 Notes: '02 Survey: C015450			DIST-0310456 1
Notes: '02 Survey: C015451 38.434211000000 -121.8355800000 007/160 SINGLE WOOD FOLE 40695294 TRI FOST Notes: '02 Survey: C015451 Total # of Attachments: 1 DIST-0310456 1 DIST-0310456 1 Notes: '02 Survey: C015450	POST (N C		
38.434211000000 -121.8355800000 007/160 SINGLE WOOD POLE 40695294 TRI FOST Completed/no problems Total # of Attachments: 1 DIST-0310456 1			
-121.8355800000 007/160 SINGLE WOOD FOLE 40695294 TRI FOST [] completed/no problems Total # of Attachments: 1 [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015450		Notes: '02 Survey: C015451	
007/160 SINGLE WOOD FOLE 40695294 TRI FOST Completed/no problems Total # of Attachments: 1			
[] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes: '02 Survey: C015450			
[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015450			Total # of Attachments: 1
[] not inspctd this patrol Notes: '02 Survey: C015450	THE PICT		DIST-0310456 1
Notes: '02 Survey: C015450			
38.434787000000			
		100003. 02 Survey: C015450	

Page 21

Inspector Name : COOPER

Date Inspected : 3-24-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	1	Attachment Type/Owner Listed
Framing Config		-11-7-0
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
007/161 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40592602	[]completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
7-1 NIC	[] not inspetd this patrol	
	Notes: '02 Survey: C015449	
38.435348000000		
-121.8345510000		
007/162 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0612569	[]completed/new finding(s)	DIST-0310456 1
RI POST T-U NIC	[]pre-existing cond chked	
• • • • • • • • • • • • • • • • • • • •	[]not inspctd this patrol	
	Notes: '02 Survey: C015448	
8.435923000000		
121.8340300000		
07/163 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0874377	[]completed/new finding(s)	DIST-0310456 1
RI 2055, — [/ .	[]pre-existing cond chked	
一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一	[]not inspctd this patrol	
•	Notes: '02 Survey: C015447	
8.436578000000		
121.8334760000	6	
07/164 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0875434	[]completed/new finding(s)	DIGE_03104E6 1
RI-POST - INIA	[]pre-existing cond chked	2251-0310456 1
T-IN/C	[]not inspctd this patrol	
•	Notes: '02 Survey: C015446	
8.437187000000	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
121.8329210000	j	
07/165 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
0816609	[]completed/new finding(s)	DIGT_02104E6 1
RI POST T-I NIC	[]pre-existing cond chked	2401.6310426 1
, , , , , ,	[]not inspctd this patrol	
	Notes: '02 Survey: C015445	
3.437740000000	Moces. Oz Burvey: C015445	
121.8324220000		
07/166 SINGLE WOOD POLE	K]completed/no problems	Total 4 of 24th 1
	[]completed/new finding(s)	Total # of Attachments: 1
1925094 12 FOST C- L MC	[]pre-existing cond chked	DISI-0310456 I
- U Pic	[] not inspetd this patrol	
	Notes: '02 Survey: C015444	
.438333000000	2 Survey: C015444	
21.8318940000	1	
7/167 SINGLE WOOD POLE		m1
759633	1 -	Total # of Attachments: 2
		CABL-UNKNOWN 1; DIST-0310456 1
T-CMC	[]pre-existing cond chked	
	[] not inspetd this patrol	
.438872000000	Notes: '02 Survey: C015443	
21.8314340000		
7/168 SINGLE WOOD POLE		Total # of Attachments: 3
759889 T_POST	[]completed/new finding(s)	CABL-UNKNOWN 1; DIST-0310456 1; STLT-UNKNOWN 1
T-(plc	Toxe-existing cond chked	1
120010	[]not inspctd this patrol	INSULATORS 244
43.04.54.00.00.00	Notes: '02 Survey: C015442 S	STREET LIGHT
.439464000000		
.21.8309530000	1	

Inspector Name : Date inspected : _

Funct Loc : ETL.6730.POLE.WOOD Order

: 41620565

60066 DIXON-VACA #1+-WOOD POLE

PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip #

Framing Config

Access:

HOST Tech ID/Equip #:

Lat: Long:

007/169 SINGLE WOOD POLE

40657513

JIM 1-T TECH TECH

38.440156000000 -121.8303120000

007/170 SINGLE WOOD POLE

TRI POST T-L NIC

38.440760000000 -121.8298060000

007/171 SINGLE WOOD POLE

40592600

TRI POST

-121.8292680000 007/172 SINGLE WOOD POLE

40868319

38.441296000000

TRI POST (-(U)

38.441931000000

-121.8287050000 007/173 SINGLE WOOD POLE

40823449

38.442518000000 -121.8282130000

007/174 SINGLE WOOD POLE 40816990

38.443096000000

38.443866000000

-121.8266740000

-121.8277020000 007/175 SINGLE WOOD POLE

40868323

-121.8272030000 007/176 SINGLE WOOD POLE

40612509

38.444253000000

[]completed/no problems rompleted/new finding(s) []pre-existing cond chked []not inspctd this patrol

POST INSUL STRESSED

Attachment Type/Owner Listed

Attachments #

Total # of Attachments: 2 completed/new finding(s) CABL-UNKNOWN 1; DIST-0310456 1

[]pre-existing cond chked []not inspetd this patrol Notes: '02 Survey: C015441

completed/no problems

Inspection Result

Notes

|completed/no problems Total # of Attachments: 2 []completed/new finding(s) CABL-UNKNOWN 1; DIST-0310456 1 []pre-existing cond chked

[]not inspctd this patrol

Notes: '02 Survey: C015440

completed/no problems Total # of Attachments: 2 [] completed/new finding(s) CABL-UNKNOWN 1; DIST-0310456 1

[]pre-existing cond chked

[]not inspctd this patrol

Notes: '02 Survey: C015439

completed/no problems Total # of Attachments: 3 []completed/new finding(s) CABL-UNKNOWN 1; DIST-0310456 1; STLT-UNKNOWN 1

[]pre-existing cond chked

[]not inspctd this patrol

Notes: '02 Survey: C015438 STREET LIGHT

|completed/no problems Total # of Attachments: 2 []completed/new finding(s) CABL-UNKNOWN 1; DIST-0310456 1 []pre-existing cond chked

[]not inspctd this patrol Notes: '02 Survey: C015437

[]sompleted/no problems []pre-existing cond chked

Total # of Attachments: 2 []completed/new finding(s) CABL-UNKNOWN 1; DIST-0310456 1

[]not inspctd this patrol Notes: '02 Survey: C015436

completed/no problems

[]pre-existing cond chked []not inspctd this patrol

Total # of Attachments: []completed/new finding(s)

Notes:

Notes:

Page 23

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Inspector Name : COOPEN Date Inspected : __

> Medium Impact Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	_	Attachment Type/Owner Listed
Framing Config		modacimient Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
007/177 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40759631	[]completed/new finding(s)	1 TOCAL # OF ACCACHMENCES:
FIELD SWITCH STRUCTURE	[] Toompreed Linding (S)	1 1 1 1
Julia Culton Sirociore	[]pre-existing cond chked	1/0000000
	I not inspetd this patrol	Kemouro, No 7/177
	Notes:	
38.444700000000		
-121.8263600000		
007/178 SINGLE WOOD POLE SW19	completed/no problems	Total # of Attachments:
41137103	[]completed/new finding(s)	" or recommency:
FIELD SWITCH STRUCTURE	[]pre-existing cond chked	
4.16 17		
5w's 17 = 19	[]not inspctd this patrol	
4	Notes:	
38.444878000000		
-121.8261090000		
007/179 SINGLE WOOD POLE SW 17	[]completed/no problems	Total # of Attachments:
40868988	[]completed new finding(s)	Total # of Accacimients:
TRI POST		
1001	pre-xisting cond chked	KEMOUED, NO7/179
	[] not inspeto this patrol	LEMOUELS, NO 1/179
	Notes:	
38.444971000000		
-121.8260250000		
008/180 LATTICE STEEL POLE	completed/no problems	Total # of Attachments:
41195902	[]completed/new finding(s)	TOTAL # OL ACCACNMENTS:
		31
	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes:	
38.445225000000		
-121.8257790000		
008/181 LATTICE STEEL POLE	completed/no problems	Total # of Attachments:
41195901	[completed/new finding(s)	Total # Of Actachments:
	(less	
	[]pre-existing cond chked	g i
	[]not inspctd this patrol	
	Notes:	
38.445685000000		
-121.8257870000	ľ	
008/182 LATTICE STEEL POLE		Total # of Attachments:
11195916	Completed/new finding(s)	TOTAL # OF ACCACHMENTS:
	t completed/new linding(s)	
	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes:	
8.446327000000		
121.8258070000	j	
08/183 LATTICE STEEL POLE	/completed/no problems	
0874397		Total # of Attachments:
OUBLE VERTICAL	[completed/new finding(s)	
COBBE VERTICAL	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes:	
8.447192000000		
121.8258000000		
08/184 LATTICE STEEL POLE	/ Isompleted/no problems	Total # of 3***
0868986	[]completed/new finding(s)	Total # of Attachments:
OUBLE VERTICAL		
	[]pre-existing cond chked	1
	[]not inspctd this patrol	
	Notes:	
8.448030000000		f
121.8257780000		

Page 24

Inspector Name : COOPEN Date Inspected : 3-2

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Accediment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Mores	
Long:	İ	
008/185 LATTICE STEEL POLE		
40816607	completed/no problems	Total # of Attachments:
DOUBLE VERTICAL	[]completed/new finding(s)	
DOOBLE VERTICAL	[]pre-existing cond chked	
	[]not inspctd this patrol	
20 4400200000	Notes:	
38.44881900000		
-121.8257700000		
008/186 LATTICE STEEL POLE	[]completed/no problems	Total # of Attachments:
40819575	[]completed/new finding(s)	
DOUBLE VERTICAL	Ipre-existing cond chked	
	[]not inspctd this patrol	KENACE LATTICE NOLO
	Notes:	REplace LATTICE Polie.
38.449642000000	1	
-121.8257480000		
008/187 LATTICE STEEL POLE	completed/no problems	Total # of Attachments:
40767512	[]completed/new finding(s)	TOTAL # OF ACCOUNTERES:
DOUBLE VERTICAL	[]pre-existing cond chked	
	[]not inspetd this patrol	g g
	Notes:	
38.450472000000	Noces.	
-121.8257190000		
008/188 LATTICE STEEL POLE	completed/no problems	
40768156	to completed/no problems	Total # of Attachments:
DOUBLE VERTICAL	[]completed/new finding(s)	
POUR VERTICAL	[]pre-existing cond chked	
	[]not inspctd this patrol	
38.451299000000	Notes:	
-121.8245910000		
008/189 LATTICE STEEL POLE		
40665509	!completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	
DOUBLE VERTICAL	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes:	
38.451270000000		
-121.8236970000		
008/190 LATTICE STEEL POLE	completed/no problems	Total # of Attachments:
10681696	[Nompleted/new finding(s)	The second
OOUBLE VERTICAL	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: HARD ANGLE TOWER LE	ANS
88.451284000000		
121.8226480000	1 _	i
008/191 LATTICE STEEL POLE		Potal # of Attachments:
0592598	[completed/new finding(s)	Total # Of Attachments:
OUBLE VERTICAL	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: GNGLE TOWER LEANS	
8.451516000000	TOWER LEAVE	
121.8213130000	1 .	
08/192 LATTICE STEEL POLE		
0601216		otal # of Attachments:
USPENSION (TWR)	[]completed/new finding(s)	
	[]pre-existing cond chked	
	[]not inspctd this patrol	<u> </u>
8.451502500000	Notes:	
121.8203355000		

Inspector Name : Coppen

Date Inspected : 3-20-12

Funct Loc : ETL.6730.POLE.WOOD

L.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	F	Attachment Mane /Or
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Noces	
Long:		
009/193 LATTICE STEEL POLE		
41195900	[]completed/no problems	Total # of Attachments:
41133300	[]completed/new finding(s)	
ľ	**Pre-existing cond chked	CONVECTORS
	[]not inspetd this patrol	
20 4544555555	Notes:	
38.451489000000	1	
-121.8193580000		
009/194 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
41374066	[]completed/new finding(s)	
1 /04	[]pre-existing cond chked	
	[]not inspctd this patrol	*
	Notes: '02 Survey: C015644	
38.452120000000		
-121.8188100000		
009/195 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40823486	[]completed/new finding(s)	ii — iii — iii — iii — iii — iii — iii — iii — iii — iii — ii
TRI PIN ARM 🗸	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes:	
38.452834000000		
-121.8181710000	1.	
009/196 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40817724	[] loompleted/new finding(s)	TOTAL # OF ACCACHMENES:
TRI PIN ARM (4(C)	[]pre-existing cond chked	
-(()()	[]not inspctd this patrol	
	Notes:	
38.45332000000		
-121.8177460000		
009/197 SINGLE WOOD POLE		Total # of Attachments:
40759629	[completed/new finding(s)	TOTAL # OF ALLACIMENTS:
TRI PIN ARM ()(C)	[lpre-existing cond chked	,
7-10	[] not inspetd this patrol	
`	Notes:	
38.453897000000	1.0000	
-121.8172250000		
009/198 SINGLE WOOD POLE	completed/no problems	Total # of the distance of the same of the
10759885	[]completed/new finding(s)	Total # of Attachments:
RI PIN ARM	I lpre-existing cond chked	
TRI PIN ARM	[]not inspctd this patrol	
- (Notes:	
38.454429000000	Notes.	
121.8167370000		
009/199 SINGLE WOOD POLE	Completed/no problems T	
0665529	[]completed/new finding(s)	Total # of Attachments:
TRI PIN ARM		
	[] pre-existing cond chked	
	[]not inspctd this patrol	
8.455100000000	Notes:	
121.8161700000		į
09/200 SINGLE WOOD POLE	(A gompleted for my	
0695469 /	completed/no problems	otal # of Attachments:
RI PIN ARM	[]completed/new finding(s)	1
	[]pre-existing cond chked	
i	[]not inspetd this patrol Notes:	
8.455676000000	NOCES:	
121.8156090000		

Page 26

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	<u> </u>	Attachment Type/Owner Listed
Framing Config	ĺ	
Access:	<u> </u>	
HOST Tech ID/Equip #:	Notes	<u> </u>
Lat:		
Long:		
009/201 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40599397	[]completed/new finding(s)	
TRI PIN ARM TIME (NIC)	[]pre-existing cond chked	
, ,	[]not inspctd this patrol	
	Notes:	
38.456269000000		
-121.8151190000		
009/202 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40601213	[]completed/new finding(s)	
TRI PIN ARM	Ipre-existing cond chked	National Aug
	[]not inspctd this patrol	REPLACE TOIE - 24KS
	Notes: MONITOR OLD SHELL R	OTTEN POLE
38.456874000000		
-121.8145560000		
009/203 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40868315	[]completed/new finding(s)	1992
TRI PIN ARM	[]pre-existing cond chked	
1.0	[]not inspctd this patrol	
	Notes:	
38.457452000000		
-121.8140690000	L.	
009/204 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40875471	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes:	
38.457998000000		
-121.8135620000	<u></u>	
009/205 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40823488	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes:	
38.458590000000		·
-121.8130010000		
009/206 SINGLE WOOD POLE		Total # of Attachments:
40817722 TRI-PIN ARM T-1 (N/C)	[]completed/new finding(s)	
TRI PIN ARM (-((M/C)	[]pre-existing cond chked	
,	[]not inspctd this patrol	
	Notes:	
38.459287000000		
-121.8124100000		
009/207 SINGLE WOOD POLE		Total # of Attachments:
40767514	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
·	[]not inspctd this patrol	
	Notes:	
88.459827000000		
-121.8119320000		
009/208 SINGLE WOOD POLE	<i>y</i>	Total # of Attachments:
.0759883	[]completed/new finding(s)	
RI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
0.1001	Notes: MONITOR SHELL ROTTEN	POLE
8.460458000000		· ·
121.8114000000	200	

Page 27

Inspector Name : Coope Date Inspected : 3-20-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Transation Bossile	
Equip #	Inspection Result	Attachments #
Framing Config		Attachment Type/Owner Listed
		THE STATE OF THE S
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
009/209 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40665510	[]completed/new finding(s)	
TRI PIN ARM TRAMP	[]pre-existing cond chked	
	[]not inspctd this patrol	
1	Notes:	7
38.461047000000		
-121.8108610000		
009/210 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40677719	[]completed/new finding(s)	
TRI PIN ARM TRAMP	fore-existing cond chked	10 1
1	[]not inspctd this patrol	Replace XAMS - 191.
1	Notes:	
38.461632000000	1	
-121.8103110000	1 .	,
009/211 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40599400	[]completed/new finding(s)	
TRI DOST TIA	[]pre-existing cond chked	
The state of the s	[] not inspetd this patrol	
	Notes:	
38.462215000000	noces.	
-121.8098090000		
010/212 SINGLE WOOD POLE	completed/no problems	Make 1 H of 244 1
41102751	[] completed/new finding(s)	Total # of Attachments:
TRI PIN ARM	[]pre-existing cond chked	
(°)	[] not inspctd this patrol	
38.462819000000	Notes:	
-121.8092750000		
		•
010/213 SINGLE WOOD POLE 40695465	1/sompleted/no problems	Total # of Attachments:
	[]completed/new finding(s)	
TRI PIN ARM T-1 (c)	[]pre-existing cond chked	
` ` ` ` ' '	[]not inspctd this patrol	
35.4600000000	Notes:	
38.463378000000		
-121.8087660000		
010/214 SINGLE WOOD POLE		Total # of Attachments:
40599399	[]completed/new finding(s)	
THI PIN ARM T-1(6)	[]pre-existing cond chked	
1	[]not inspctd this patrol	
	Notes:	
38.464001000000		
-121.8082160000		
010/215 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40590224	[]completed/new finding(s)	
TRI PIN ARM TRAMP	[]pre-gristing cond chked	
	[]not enspetd this patrol	
-	Notes:	
38.464588000000	1	
-121.8076650000		
010/216 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40874399	completed/new finding(s)	
TRE POST ((C)	[]pre-existing cond chked	
× - /	[]not inspctd this patrol	1
	Notes:	
38.465192000000		
-121.8072100000		
	L	

Page 28

Inspector Name : ___ Date Inspected : _

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	imapection Result	Attachment Type/Owner Listed
Framing Config		Accacimilate Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		*
Long:		
010/217 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40875463	[]completed/new finding(s)	
TRI POST PA	[]pre-existing cond chked	
T (1"	[]not inspctd this patrol	
1	Notes:	
38.465775000000		
-121.8066190000		
010/218 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:
40816605	[]completed/new finding(s)	
TRI FIN ARM	[]pre-existing cond chked	
]	[]not inspctd this patrol	
	Notes:	
38.466309000000		
-121.8061680000		
010/219 SINGLE WOOD POLE 40825155	completed/no problems	Total # of Attachments:
	[]completed/new finding(s)	
THE PEN ARM TIL (NIC)	[]pre-existing cond chked	
	[]not inspctd this patrol	
38.466777000000	Notes:	
-121.8057490000		
010/220 SINGLE WOOD POLE	[]completed/no problems	
40759627	[]completed/new finding(s)	Total # of Attachments:
TRI PIN ARM	pre-existing cond chked	
,	[]not inspetd this patrol	Ray Day Day
	Notes: ACROSS FROM 2010 MON	BOND WIRE BROKEN - 19n
38.467110000000	The state of the state s	
-121.8054380000		
010/221 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40768153	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes:	
38.467352000000		
-121.8052370000		
010/222 SINGLE WOOD POLE		Total # of Attachments:
40657509	[]completed/new finding(s)	1
TRI PIN ARM T ((c)	[]pre-existing cond chked	1
	[]not inspctd this patrol	
38.467709000000	Notes:	
-121.8049400000		
010/223 SINGLE WOOD POLE	Teampleted/no problems	Total # of Attachments.
40599402	[]completed/new finding(s)	Total # of Attachments:
CRIANGLE POST 767 LL (C)	[]pre-existing cond chked	
(47)	[] not inspctd this patrol	
	Notes:	
38.468701000000		
121.8040530000	_/	
010/224 SINGLE WOOD POLE		Total # of Attachments:
10601210	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes:	
8.46923300000	Notes:	
8.469233000000 121.8035400000	Notes:	

Page 29

Inspector Name : Cooper Date Inspected : 3-a-r

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact
Detailed Ground Inspections

Equip # Premaing Config Access: Notes Lat: Long:	Desc of Tech ID	Inspection Result	Attachments #
Framing Config Access: BOST Tech ID/Equip #: Lat: Long			
Access: EOST Tech ID/Equip #: Lat: Long: Clorys SINNLE MODD FOLE Clory SINNLE MODD FOLE Clory Sinnle Modd Fole Clory Sinnle Modd Fo			Accaemment Type/Owner Listed
Lat: Long: 1010/223 SIRMLE WOOD FOLE 40868314 33.469729000000 1-121.8031380000 36.470790000000 1-221.8031380000 26.000014 Hold patrol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extrac			
Lat: Long: 1010/223 SIRMLE WOOD FOLE 40868314 33.469729000000 1-121.8031380000 36.470790000000 1-221.8031380000 26.000014 Hold patrol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: NONTON NOTES POLE 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost importd this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extracting cond chicked lost import this jearnol Notes: 1 pre-extrac	HOST Tech ID/Equip #:	Notes	
Longs A03/233 MEMIC WOOD FOLE (1 completed/no probless (1 per-existing cond chied (1 not inspect this patrol Notes: 12.803133000 12.1.803130000 13.469799000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 13.470790000000 14.4809000000 15.470790000000 16.473313000000 17.4809000000 18.477080000000 19.473515000000 19.473515000000 10.5737 SIRKLE WOOD FOLE (1 completed/no probless (1 completed/no probless (1 per-existing cond chied (1 per-existing		21000	
Completed/no problems Total # of Attachments: Completed/no problems Total # of Attachments: Completed/no problems		1.	
Completed/new finding(s) Description Total # of Attachments: T		lcompleted/no problems	Imph-2 II - C 2
1 pre-extisting cond dished 1 pre-extisting cond dishe			
Linerinspect this parrol Notes:	1		*
38.46972900000 -121.8031310000 1271.8031310000 138.470790000000 138.470790000000 138.470790000000 138.470790000000 138.470790000000 138.470790000000 138.470790000000 138.470790000000 121.80318900000 122.80318900000 122.80318900000 123.80318900000 123.80318900000 123.80318900000 124.80318900000 125.80318900000 126.80318900000 127.80318900000 138.4708000000 138.4708000000 138.47080000000 138.4800000000 138.48000000000 138.4800000000000000000000000000000000000	(3,0)		
38.48729000000 39.472379000000 30.1724795000000 30.17247950000000 31.21.8031330000 32.4707900000000 32.121.80313900000 32.1721.803138000000000 33.471395000000 33.471395000000 33.471395000000 33.471395000000 34.713950000000 33.4713950000000 34.71395000000000 34.713950000000000 33.4713950000000000 33.4713000000000000 33.4713000000000000 33.4713000000000000000000000000000000000000			
121.80013330000 132.8013018 WOD POLE 40816503 TRI POST TEmpleted/now Yinding (s) pre-evainting cond cheed property	38.469729000000	noces.	
Completed/now Finding(s) Total # of Attachments: Total # of Atta			
TEMPLOCAGINES HANDERS TEMPLOCAGINES HANDERS TOTAL # of Attachments: Total # of Attachment		[[completed/ng problems	Total # of Attachments
I pre-existing cond chked I not inspect this patrol			
I Inct Import	TRI POST		
Notes: Scijht Rdt Lim 10/28 SHGLE WOD POLE 1 completed/no problems Total # of Attachments: 1 completed/new finding(s) 1 completed/new fi			
38.470790000000 10/228 SINGLE WOOD POLE 1 completed/no problems Total # of Attachments:			
121.8021990000 Completed/no problems Completed/n	38.47079000000		
Completed/no problems Total # of Attachments: Completed/no problems Co)	Lishe (Yole Light
Completed/new finding(s) Completed/new finding(s)	010/228 SINGLE WOOD POLE		
TRI PIN ARM Pre-existing cond chied Inot inspect this patrol Notes:		· · · · · · · · · · · · · · · · · ·	TOTAL # OI ALLACIMENTS:
Tinot inspect this patrol Notes:	TRI PIN ARM		
38.473395000000 -121.8015890000 1010/229 SINGLE WOOD FOLE 40761498 FAIT PIN ARM		Tent inenetd this natural	1
38.473395000000 -121.8015890000 1010/229 SINGLE WOOD FOLE 40761498 FAIT PIN ARM			LEADING FOIC - 19x
Completed/no problems Total # of Attachments:	38.471395000000		
### DTN ARM THAC Ipre-existing cond chked Ipre-existing cond chked Inot inspect this patrol	-121.8015890000		
### DTN ARM THAC Ipre-existing cond chked Ipre-existing cond chked Inot inspect this patrol	010/229 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments
	40761498	Completed/new finding(e)	Total # Of Actachments:
I not inspect this patrol Notes: MONITOR ROTTEN POLE	TRI PIN ARM (L+ (C)		
38.47208000000 -121.8010520000 38.472609000000 -121.8005420000 1010/230 SINGLE WOOD FOLE (WIC) 38.473129000000 -121.80007100000 -121.80007100000000000000000000000000000000			REPOLACE DIE POLS SETTEN FOR
38.47208000000 -121.8010520000 38.472609000000 -121.8005420000 1010/230 SINGLE WOOD FOLE (WIC) 38.473129000000 -121.80007100000 -121.80007100000000000000000000000000000000			100000000000000000000000000000000000000
O10/230 SINGLE WOOD FOLE 4075981 I completed/no problems I completed/no problems I lemant of this patrol Notes: Total # of Attachments: I completed/no problems I lemant of this patrol Notes: Total # of Attachments: Total # of Attachments: Total # of Attachments: Total # of Attachments: Total # of Attachments: Total # of Attachments: Total # of Attachments: Total # of Attachments: Total # of Attachments: Total # of Attachments: I completed/no problems I lemant inspect this patrol Notes: Total # of Attachments:	38.472008000000	The second secon	and the second s
Completed/new finding(s) I pre-existing cond chked Inot inspect this patrol	-121.8010520000		
	010/230 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments
I pre-existing cond chked Inot inspect this patrol	40759881	[] completed/new finding(s)	TOTAL # OF ACCACHMENTS:
Notes: Notes: Notes: Notes: 121.8005420000	TRI DIN ARM		
Notes: Notes: Notes: Notes: 121.8005420000	- (-\ (p/e)		
38.472609000000 -121.8005420000 1010/231 SINGLE WOOD FOLE 10665513 RT FOST 10 completed/no problems 1 local # of Attachments: 1 lompleted/no problems 1 limited inspect this patrol Notes: 121.8000710000 1010/232 SINGLE WOOD POLE 10677715 RT FIN ARM TRAMP 3HPD (M/c) 8.473721000000 101/233 SINGLE WOOD FOLE 121.7995520000 107/233 SINGLE WOOD FOLE 1 local # of Attachments: 1 completed/no problems 1 local # of Attachments: 2 local # of Attachments: 3 local # of Attachments: 3 local # of Attachments: 3 local # of Attachments: 3 local # of Attachments: 3 local # of Attachments: 4 local # of Attachments: 5 local # of Attachments: 6 local # of Attachments: 7 local # of Attachments: 8 local # of Attachments: 8 local # of Attachments: 9 l	,		
Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: Completed/new finding(s) Description of the patrol Notes: Completed/new finding(s) Description of the patrol Notes: Completed/new finding(s) Description of the patrol Completed/new finding(s) Description of the patrol of the patrol Description of the patrol o	38.472609000000		
[] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: 100/232 SINGLE WOOD POLE Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 2 Completed/no problems Total # of Attachments: 3 Completed/no problems Total # of Attachments: 3 Completed/no problems Total # of Attachments: 2 Completed/no problems Total # of Attachments: 3 Completed/no problems Total # of Attachments: 3 Completed/no problems Total # of Attachments: 4 Completed/no problems Total # of Attachments: 5 Completed/no problems Total # of Attachments: 6 Completed/no problems Total # of Attachments: 6 Completed/no problems Total # of Attachments: 6 Completed/no problems Total # of Attachments: 7 Completed/no problems Total # of Attachments: 8 Completed/no problems Total # of Attachments: 9 Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 1 Completed/no problems Total # of Attachments: 2 Completed/no problems Total # of Attachments: 3 Completed/no problems Total # of Attachments: 4 Completed/no problems Total # of Attachments: 5 Completed/no problems Total # of Attachments: 6 Completed/no problems Total # of Attachments: 7 Completed/no problems Total # of Attachments: 8 Completed/no problems Total # of Attachments:	-121.8005420000		ì
	010/231 SINGLE WOOD POLE	Completed/no problems I	Total # of Attachments
[]pre-existing cond chked []not inspect this patrol Notes: 121.8000710000 122.8000710000 123.8000710000 121.8000710000 121.8000710000 121.8000710000 121.80007100000 121.7995520000 121.7995520000 121.7995520000 121.7995520000 121.7995520000 121.800071000000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.80007100000 121.800071000000 121.80007100000 121.80007100000 121.80007100000 121.800071000000 12			1 Of Meddennesses,
Notes: Notes:	TRE FOST		
Notes: Notes:	(2((0,0)		
121.8000710000 1010/232 SINGLE WOOD POLE 10677715 RI PIN ARM TRAMP 3+473721000000 121.7995520000 1010/233 SINGLE WOOD POLE 0592597 RI PIN ARM TCAMP 0592597 RI PIN ARM TCAMP 0592597 RI PIN ARM TCAMP 0592597 RI PIN ARM TCAMP 069250000 18.474355000000 18.474355000000 19.00000000000000000000000000000			
Completed/no problems Total # of Attachments: Completed/no problems Total # of Attachments: Completed/no problems	88.473129000000		i
[] completed/new finding(s) [] pre-existing cond chked [] Inot inspctd this patrol Notes: 1	121.8000710000	_	
[] completed/new finding(s) [] pre-existing cond chked [] Inot inspctd this patrol Notes: 1	10/232 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments
[]pre-existing cond chked []not inspctd this patrol Notes: 1			Industriculus.
8.473721000000 121.7995520000 10/233 SINGLE WOOD POLE 0592597 RI FIN NEW T (V/c) 8.474355000000 []not inspctd this patrol Notes: Total # of Attachments: lcompleted/new finding(s)			· I
8.473721000000 121.7995520000 10/233 SINGLE WOOD POLE	3HPM (NK)		
8.473721000000 121.7995520000 10/233 SINGLE WOOD FOLE 0592597 RI FIN TEM T (N/C) 8.474355000000 1 Completed/no problems Total # of Attachments:	シベン ひ・)	I	
10/233 SINGLE WOOD FOLE Completed/no problems Total # of Attachments: Completed/new finding(s) I pre-existing cond chked I not inspect this patrol Notes: Right Moderation Notes N	8.473721000000	1	
0592597 RI FIN 1844 T-\(\(\mathcal{V}\)C\) [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:	121.7995520000		
0592597 RI FIN ARM T_\(N/C) [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes:	10/233 SINGLE WOOD POLE		Total # of Attachments:
[] pre-existing cond chked [] not inspetd this patrol Notes:		<i>F</i> " ' "	
[Inot inspctd this patrol Notes:	RE PIN 12M T_\(N/c)	1 7 7	
Notes:			
121.7989750000	8.474355000000		
	121.7989750000		

Page 30

Inspector Name : Cooren Date Inspected: 3-23-17

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
010/234 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40592595	[]completed/new finding(s)	
TRI POST	Tree-existing cond chked	
	[] not inspctd this patrol	The state of the s
1	Notes:	Insulations - 2ym
38.474972000000	Noces:	·
-121.7984530000		
010/235 SINGLE WOOD POLE	Trompleted/no problems	
40612589		Total # of Attachments:
TRIANGLE POST 70	[]completed/new finding(s)	
TRIANGLE POST 70 (312)	[]pre-existing cond chked	4
LY (MS)	[]not inspetd this patrol	
28 475584000000	Notes:	
38.475584000000	1	1.
-121.7979030000		
010/236 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40874401	[]completed/new finding(s)	
TRIANGLE POST 10	[]pre-existing cond chked	- [i
てんめ	[]not inspctd this patrol	
	Notes: Structure is FIELD S	SWITCH STRUCTURE
38.476174000000	No separate pole red	cord required
-121.7973790000	Deleted record 5/4/0	02 M. Lane 720-7105
010/237 LATTICE STEEL POLE SW		Total # of Attachments:
40868984	[]completed/new finding(s)	
FIELD SWITCH STRUCTURE	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT; LINE TR	[]not inspetd this patrol	* Due our size aliza
	Notes: TRI PIN ARM	* Duy our Switch platform
38.476758000000		
-121.7968730000		
A006/156 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40695331	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	222 0310430 1
T-161	[]not inspetd this patrol	
	Notes: '02 Survey: C015693	
38.346418000000	2 aurvey: C015693	
-121.9135160000		1
A006/157 SINGLE WOOD POLE	Name late of the l	
40657532		Total # of Attachments: 1
=000/33Z	[]completed/new finding(s)	DIST-0310456 1
T-16)	[]pre-existing cond chked	1
() / – /	[]not inspctd this patrol	
	Notes: '02 Survey: C015694	
38.345812000000	1	
-121.9140610000		
A006/158 SINGLE WOOD POLE		Total # of Attachments: 1
40768118	[]completed/new finding(s)	DIST-0310456 1
TOST TOST	[]pre-existing cond chked	
` ` ` ` ` `	[]not inspctd this patrol	
	Notes: '02 Survey: C015695	
38.345216000000		· · · · · · · · · · · · · · · · · · ·
-121.9145820000		İ
A006/159 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40767453	[]completed/new finding(s)	DIST-0310456 1
3 HORIZONTAL POST DELTA	[]pre-existing cond chked	
	[]not inspetd this patrol	<u> </u>
	Notes: '02 Survey: C015696	
38.34466800000	52 Barvey. Co13636	
-121.9152040000		ļ

Page 31

Inspector Name : COOPER Date Inspected : $3 - \lambda 3 - 12$

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A006/160 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40810284	(lcompleted/new finding(s)	
TRI PIN ARM DEAD END	Ipre-existing cond chked	KO
	[]not inspctd this patrol	KShara All Salis
	Notes: '02 Survey: C015697	Shittle Jos Spice
38.344179000000		
-121.9155240000		
A006/161 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40816621	[]completed/new finding(s)	1
TRI PIN ARM DEAD END	Pre-existing cond chked	* CONNECTIONS * SMUTGEY SPLICE 245
1	[]not inspetd this patrol	& Show Thuy Splice 248
	Notes: '02 Survey: C015698	
38.343247000000	_	
-121.9155640000	ريا	¥
A006/162 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40875415	[] completed/new finding(s)	
TRI PUST	[]pre-existing cond chked	
(e)	[]not inspctd this patrol	
¥ -	Notes: '02 Survey: C015699	
38.342705000000		
-121.9160320000		
A006/163 SINGLE WOOD POLE		Total # of Attachments:
40874371 TRI FOST	[]completed/new finding(s)	
TRI POST V—V (U)	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015700	
38.342107000000		
-121.9165690000	16.	
A006/164 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40612528	[]completed/new finding(s)	, at Medicinents
TRI POST ()	[]pre-existing cond chked	
- 64	[]not inspetd this patrol	
	Notes: '02 Survey: C015701	
38.341463000000		
-121.9171170000		
A006/165 SINGLE WOOD POLE		Total # of Attachments:
40599337	[]completed/new finding(s)	saconnegger.
3 HORIZONTAL POST DELTA	[]pre-existing cond chked	
ζ,	[]not inspctd this patrol	
	Notes: '02 Survey: C015702	
8.340805000000		
121.9177000000		
1006/166 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
0660479	[]completed/new finding(s)	. Ja Cookinglies.
RIANGLE POST 70	[]pre-existing cond chked	
てたら	[]not inspctd this patrol	
10-	Notes: '02 Survey: C015703	
8.340262000000		
121.9181970000		
006/167 SINGLE WOOD POLE		otal # of Attachments:
0665494	[]completed/new finding(s)	Industrience.
RI POST	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015704	
8.339644000000		

Page 32

Inspector Name :

Date Inspected : _

Funct Loc: ETL.6730.POLE. Order: 41620565		CA #1+-WOOD POLE	Medium Impact
. 41020363	PATR/INSP 60066 DIX	ON-VACA #1+	Detailed Ground Inspection
Desc of Tech ID	Inspection Result	Attachments #	
quip #	_	Attachment Type/Owne	r Listed
raming Config		1250,000	- 425004
ccess:			
OST Tech ID/Equip #:	Notes		
at:			
ong:			
006/168 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:	
CIANGLE POST 70	[]completed/new finding(s)		
CIANGLE POST /0	[]pre-existing cond chked		
	[]not inspetd this patrol		
3.339026000000	Notes: '02 Survey: C015705		
21.9192980000			
06/169 SINGLE WOOD POLE	completed/no problems	Potes I # of 744	
767455	[]completed/new finding(s)	Total # of Attachments:	
IANGLE POST 70	[]pre-existing cond chked		
	[] not inspetd this patrol	1	
	Notes: '02 Survey: C015706		
.338428000000	• 255-1		
21.9198260000			
06/170 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:	
810286	[]completed/new finding(s)		
I POST	[]pre-existing cond chked		
	[]not inspctd this patrol		İ
32500000000	Notes: '02 Survey: C015707		
.33782300000			ł
21.9203530000 07/171 SINGLE WOOD POLE			
816623	completed/no problems	Total # of Attachments:	
AT PIN ARM	[]completed/new finding(s) []pre-existing cond chked		
	[]not inspctd this patrol		
	Notes: '02 Survey: C015708		
.337269000000	22 Barvey. Co13708		
21.9208650000	1.		
07/172 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:	
868998	(completed/new finding(s)	" or recommency.	
AT PIN ARM	[]pre-existing cond chked		
	[]not inspctd this patrol		
	Notes: '02 Survey: C015709		
33663900000	Pole HAS "	. 11 /	*
1.9214440000	1018 (4 AS	- Ivass	
7/173 SINGLE WOOD POLE 74347	completed/no problems	Total # of Attachments:	
ANGLE POST 70	[] dompleted/new finding(s)		ļ
200211 70	[]pre-existing cond chked		
	[]not inspctd this patrol Notes: '02 Survey: C015710		
336229000000	· —		
1.9218890000	Pole HAS"	C" Kunsc	
7/174 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments:	
92617	[Acompleted/new finding(s)	- σουτ π οι Allaciments:	
POST	[]pre-existing cond chked		
	[]not inspctd this patrol		i
	Notes: '02 Survey: C015711		
335903000000			
.9222130000			
7/175 SINGLE WOOD POLE	[]completed/no problems []	Total # of Attachments:	
95335	[]completed/new finding(s)		
POST	pre-existing cond chked	1000	1
	[]not inspetd this patrol	LEANING POLE -	-14K
335307000000	Notes: '02 Survey: C015712	J 1	

Page 33

Inspector Name : COOPER Date Inspected: <u>3ー入3ー12</u>

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Inspection Result	Attachments #
	Attachment Type/Owner Listed
	Procedurenc Type/owner histed
Notes	
Notes	
L loom3 sted/se hlane	
	Total # of Attachments:
	1
I]not inspetd this patrol	LANIN POLE
Notes: '02 Survey: C015713	
<u></u>	
	Total # of Attachments:
[]pre-existing cond chked	
[]not inspetd this patrol	
Notes: '02 Survey: C015714	
completed/no problems	Total # of Attachments:
[]completed/new finding(s)	
[]pre-existing cond chked	
[]not inspctd this patrol	
Notes: '02 Survey: C015715	
completed/no problems	Total # of Attachments:
	,
12 022107 0025720	
	*
Completed/no problems	Total # of Attachments:
	TOTAL # OF ACCACIMIENTS:
l des 102 aurvey: Cois/i/	
Mompleted/pp problems	Total # of all all
	Total # of Attachments:
Notes: '02 Survey: C015718	
	Total # of Attachments:
_	
	
Notes: '02 Survey: C015719	
9007	
_	
	Total # of Attachments:
[]completed/new finding(s)	
[]pre-existing cond chked	
[]not inspetd this patrol	
[] HOL THE DECKOT	
Notes: '02 Survey: C015720	
	[]pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015715 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015716 Completed/no problems []Completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015717 Completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015718 Completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015718 Completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015719

Page 34

Inspector Name : COOPER

Date Inspected : 3-23-12

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	•	Attachment Type/Owner Listed
Framing Config		Treatment labelowner Fisted
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	110000	
Long:		
A007/184 SINGLE WOOD POLE		
40599339		Total # of Attachments:
	[]completed/new finding(s)	
ERI POST (NIC)	[]pre-existing cond chked	
, , ,	[]not inspctd this patrol	
- 0415 - 2017US	Notes: '02 Survey: C015721	
38.329772000000		
-121.9275980000	_ 3	
A007/185 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40677735	[]completed/new finding(s)	199
TRI POST (C)	[]pre-existing cond chked	
, ,	[]not inspctd this patrol	
	Notes: '02 Survey: C015722	
38.329235000000	1.1	
121.9280400000		
A007/186 SINGLE WOOD POLE	[] completed/no problems	Total # of Attachments: 1
10665444	[]completed/new finding(s)	DICT_0310456 1
	[]pre-existing cond chked	DT01.00T0#20 T
TI (prc)	[] not inspetd this patrol	
((())		
88.328649000000	Notes: '02 Survey: C015723	
121.9285620000		
.007/187 SINGLE WOOD POLE 0759905	Completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
RI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
2000	Notes: '02 Survey: C015724	
8.328046000000		
121.9291090000		
007/188 SINGLE WOOD POLE	[completed/no problems	Total # of Attachments: 1
0767457	[]completed/new finding(s)	DIST-0310456 1
PI POST T-1(c)	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015725	
8.327447000000		
121.9296440000		
007/189 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0817738		DIGT_0010456 1
RI DOST 10.	[]pre-existing cond chked	TD1-0310430 T
THEY	1	
· · · · · · · · · · · · · · · · · · ·	[] not inspetd this patrol	
3.326907000000	Notes: '02 Survey: C015726	
.326907000000 L21.9301890000	1	
007/190 SINGLE WOOD POLE	/completed/no problems	Total # of Attachments: 1
9816625	() completed/new finding(s)	DIST-0310456 1
	[]pre-existing cond chked	w
T-1(c)	[]not inspctd this patrol	
•	Notes: '02 Survey: C015727	
.326308000000		
21.9306600000		
08/191 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
875417	[]completed/new finding(s)	
T POST (6)	[]pre-existing cond chked	4
TH(6)	[] not inspetd this patrol	
- /	Notes: '02 Survey: C015728	
.325700000000	102 Survey: C015728	
21.9311850000		

Page 35

Funct Loc: ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Inspector Name : CoopeR

Date Inspected: 3-23-12

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:	1	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	1 -	
A008/192 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40874381	[]completed/new finding(s	DIGE 0310456 1
TRI POST	[]pre-existing cond chked	
	[] not inspetd this patrol	
ľ	Notes: '02 Survey: C015729	
38.325132000000	100003: 02 Survey: C013/23	
-121.9317300000		
A008/193 SINGLE WOOD POLE	Completed/no problems	
40612531	[]completed/new finding(s)	Total # of Attachments: 1
3 HORIZONTAL POST DELTA SHORT	[]pre-existing cond chked	DIST-0310456 1
Toba Balla Block		
	[]not inspetd this patrol	· ·
38.324539000000	Notes: '02 Survey: C015730	
-121.9322460000		
A008/194 SINGLE WOOD POLE		
40592618	completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspetd this patrol	
D	Notes: '02 Survey: C015731	
38.323942000000		
-121.9327330000		
A008/195 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40599340	[Acompleted/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015732	
38.323358000000	MONITOR LEANING POL	E .
-121.9332730000		
A008/196 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40695402	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015733	
38.322756000000	1	•
-121.9338620000		•
A008/197 SINGLE WOOD POLE		Total # of Attachments: 1
40665446	[] completed/new finding(s)	DIST-0310456 1
PT PIN APN T- (Co)	[]pre-existing cond chked	
,	[]not inspctd this patrol	}
	Notes: '02 Survey: C015734	
38.322439000000		
-121.9340510000		1
A008/198 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
10759907	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspetd this patrol	•
	Notes: '02 Survey: C015735	
8.321868000000	12 232 70 7 . 6013 733	
121.9345870000		
.008/199 SINGLE WOOD POLE		Total # of Attachments 1
0759656	completed/new finding(s)	Total # of Attachments: 1
RIANGLE POST 70	[]pre-existing cond chked	DISI-0310426 1
2 . v	[]not inspctd this patrol	
	Notes: '02 Survey: C015736	
0.30100000000	Noces: '02 Survey: C015736	
8.321282000000		
8.321282000000 121.9351050000		

Page 36

Inspector Name : Coopek Date Inspected: 2-24-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		
	<u> </u>	Attachment Type/Owner Listed
Framing Config	ľ	
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:	2	
		577
A008/200 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40817740	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015737	
38.320703000000	MONITOR LEANING POL	
-121.9356300000	L	
A008/201 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40823466	[]completed/new finding(s)	
TRIANGLE POST 70	[]pre-existing cond chked	2101 0310430 1
	-	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015738	
38.320094000000		j
-121.9361580000		
A008/202 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40869002	[]completed/new finding(s)	DIGE 2310456 1
		DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015739	
38.319531000000	(3)	
-121.9366820000		
A008/203 SINGLE WOOD POLE	3 3 -+ - 3 (
	completed/no problems	Total # of Attachments: 1
40868337	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015740	
38.318917000000	100000. 02 Barvey. C013740	
-121.9372190000		
A008/204 SINGLE WOOD POLE	rompleted/no problems	Total # of Attachments: 1
40612534	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
97,0243.25	[]not inspetd this patrol	
	Notes: '02 Survey: C015741	
20 27 27 27 27 27 27 27 27 27 27 27 27 27	Notes: '02 Survey: C015741	
38.318287000000		
-121.9377690000		
A008/205 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40592620	[]completed/new finding(s)	
TRIANGLE POST 70	[]pre-existing cond chked	
	-	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015742	
38.317734000000		
-121.9382870000		
A008/206 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40695339	[]completed/new finding(s)	
TRIANGLE POST 70		DIGI-0310430 T
INIMOUS POST /U	[]pre-existing cond chked	
	[]not inspetd this patrol	· ·
	Notes: '02 Survey: C015743	
38.317104000000		
-121.9388200000		
A008/207 SINGLE WOOD POLE	completed/no problems	Total # of Attachments 2
		Total # of Attachments: 1
40665483	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015744	
38.316551000000		
-121.9392970000		
202.30323.0000		

Page 37

Inspector Name : COOPER Date Inspected: 2-24-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Equip # Framing Config Access: HOST Tech ID/Equip #: Notes	achments # cachment Type/Owner Listed
Framing Config Access: HOST Tech ID/Equip #: Notes	-acmuent lybe/Owner Fisted
Access: HOST Tech ID/Equip #: Notes	
HOST Tech ID/Equip #: Notes	
Lat:	
Long:	
3000/000	
1000	11 # of Attachments: 1
1 Teompteted/ new limiting (s) Disi	!-0310 4 56 1
1 1P-0 CAIBCING CONG CINED	
[] not inspetd this patrol	
Notes: '02 Survey: C015745	
38.316032000000	
-121.9397570000	
A008/209 SINGLE WOOD POLE [/] completed/no problems Total	l # of Attachments: 1
40759657 Completed/new finding(s) DIST	-0310456 1
TRI PIN ARM	CTUSS INSTANCE - NEEDS BANDING
[]not inspetd this patrol	LOSTATION - NEEDS ! AND US
Notes: '02 Survey: C015746	
38.315651000000	-
-121.9401050000	
A008/210 SINGLE WOOD POLE [ompleted/no problems Total	l # of Attachments: 1
40825147 []completed/new finding(s) DIST-	-0310456 1
TRI POST []pre-existing cond chked	
[]not inspctd this patrol	
Notes: '02 Survey: C015747	
38.315217000000	
-121.9404930000	A .
A008/211 SINGLE WOOD POLE Completed/no problems Total	l # of Attachments: 1
40816627 [] completed/new finding(s) DIST-	-031,0456 1
TRI PIN ARM []pre-existing cond chked	
[]not inspctd this patrol	
Notes: '02 Survey: C015748	
38.314661000000	1
-121.9408950000	
A008/212 SINGLE WOOD POLE Completed/no problems Total	# of Attachments: 1
40875419 Completed/new finding(s) DIST-	-0310456 1
TRIANGLE POST 70 []pre-existing cond chked	0010430 T
[]not inspetd this patrol	
Notes: '02 Survey: C015749	
38.314173000000	•
-121.9413130000	
	# of Attachments: 1
40868339 [] completed/new finding(s) DIST-	T OA Actaenments: 1
TRIANGLE POST 70 []pre-existing cond chked	0310456 1
[] not inspetd this patrol	j
Notes: '02 Survey: C015750	
38.313626000000	
-121.9417320000	į
40612537 Completed/new finding(s) DIST-(# of Attachments: 1
TRIANGLE POST 70 [] pre-existing cond chked	U31U456 1
[] not inspetd this patrol	
Notes: '02 Survey: C015751	
Notes: '02 Survey: C015751 38.313104000000	
-121.9420870000	
Para Para	# of Attachments: 1
r resultated the results (8) Bist-(0310456 1
TRI POST []pre-existing cond chked	
[]not inspetd this patrol	
Notes: '02 Survey: C015752 38.312552000000	
30.312332000000	
-121.9424010000	

Page 38

Inspector Name : Cooper Date Inspected : 3-23-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Tribpection Repute	Attachment Type/Owner Listed
Framing Config		Accadimient Type/Owner Listed
Access:		
	37-4-	
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A009/216 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40677740	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspetd this patrol	,,
	Notes: '02 Survey: C015753	
38.312031000000	-	·
-121.9427720000		
A009/217 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40599343	[]completed/new finding(s)	DTGT_0310456_1
TRI POST	[]pre-existing cond chked	320400 1
	[] not inspetd this patrol	
	··	
38.311503000000	Notes: '02 Survey: C015754	
1		
-121.9430910000		
A009/218 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40677744	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015755	
38.310894000000		
-121.9434760000		
A009/219 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40665448	Decompleted/new finding(s)	
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspctd this patrol	* Koolace Kin S-1 A. D.
•	Notes: '02 Survey: C015756	A TREMICE FULL TUB AUD RUSTS
38.310244000000		Files - X's UP/R TIPACKS !!
38.310244000000 -121.9438960000	, , , , , , , , , , , , , , , , , , , ,	Guys - X's OR/R TRACKS
-121.9438960000		, ,
-121.9438960000 A009/220 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments; 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121		Total # of Attachments; 1
-121.9438960000 A009/220 SINGLE WOOD POLE	Completed/no problems completed/new finding(s) pre-existing cond chked	Total # of Attachments; 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121		Total # of Attachments; 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT	Completed/no problems completed/new finding(s) pre-existing cond chked	Total # of Attachments; 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000		Total # of Attachments; 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000		Total # of Attachments: 1 DIST-0310456 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE		Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459	Completed/no problems completed/new finding(s) pre-existing cond chked not inspctd this patrol Notes: '02 Survey: C015757	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70		Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70	Completed/no problems completed/new finding(s) pre-existing cond chked not inspctd this patrol Notes: '02 Survey: C015757	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes: '02 Survey: C015757 [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70	Completed/no problems	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 78	Completed/no problems	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 78	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes: '02 Survey: C015757 [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes: '02 Survey: C015758	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 78 38.308845000000 -121.9444390000	Completed/no problems completed/new finding(s)	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE		Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015757 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015758 Completed/no problems [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD FOLE 40767459 TRIANGLE POST 78 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD FOLE 40817742	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015757 [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015758 [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015757 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015758 Completed/no problems [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE DOST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70 38.308387000000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015757 [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015758 [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD FOLE 40817742 TRIANGLE POST 70 38.308387000000 -121.9447010000	[] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015757 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015758 Completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015759	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL FOST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE FOST 70 38.308387000000 -121.9447010000 A009/223 SINGLE WOOD POLE	[] completed/no problems [] lcompleted/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015757 [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015758 [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015759 [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015759	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70 38.308387000000 -121.9447010000 A009/223 SINGLE WOOD POLE 40823430	[]completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015757 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015758 Completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015759 Completed/new finding(s) Completed/new finding(s) Completed/no problems []completed/no problems []completed/no problems []completed/new finding(s)	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL FOST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE FOST 70 38.308387000000 -121.9447010000 A009/223 SINGLE WOOD POLE	[] completed/no problems [] lcompleted/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015757 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015758 Completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015759 Completed/new finding(s) [] pre-existing cond chked [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70 38.308387000000 -121.9447010000 A009/223 SINGLE WOOD POLE 40823430	[]completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015757 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015758 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015759 Completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD FOLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70 38.308387000000 -121.9447010000 A009/223 SINGLE WOOD POLE 40823430 PRIANGLE POST 70	[] completed/no problems [] lcompleted/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015757 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015758 Completed/new finding(s) [] pre-existing cond chked [] not inspect this patrol Notes: '02 Survey: C015759 Completed/new finding(s) [] pre-existing cond chked [] completed/no problems [] completed/new finding(s) [] pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70 38.308387000000 -121.9447010000 A009/223 SINGLE WOOD POLE 40823430	[]completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015757 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015758 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015759 Completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1
-121.9438960000 A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT 38.309584000000 -121.9440140000 A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70 38.308845000000 -121.9444390000 A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70 38.308387000000 -121.9447010000 A009/223 SINGLE WOOD POLE 40823430 PRIANGLE POST 70	[]completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015757 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015758 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol Notes: '02 Survey: C015759 Completed/no problems []completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspect this patrol	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1

Page 39

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Inspector Name : COOPER

Date Inspected:

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		Treatment Type, Owner Histad
Access:		
HOST Tech ID/Equip #:	Notes	<u></u>
Lat:		
Long:		
A009/224 SINGLE WOOD POLE	[rempleted/no problems	Total # of Attachments: 1
40869004	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE FOST 70 ->	[]pre-existing cond chked	
THE	[]not inspctd this patrol	
-(40	Notes: '02 Survey: C015761	
38.307099000000	_	
-121.9454710000		
A009/225 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40874351	completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015762	
38.306506000000		
-121.9458310000		
A009/226 SINGLE WOOD POLE	lecmpleted/no problems	Total # of Attachments: 1
40601234 TRI FIN ARM.	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	
<i>U</i>	[]not inspetd this patrol	
38.305791000000	Notes: '02 Survey: C015763	
-121.9462630000		*
A009/227 SINGLE WOOD POLE	1 2 1 /	
40599345	completed/no problems	Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s) []pre-existing cond chked	DIST-0310456 1
The same same	[]not inspetd this patrol	
	Notes: '02 Survey: C015764	
38.305094000000	10003. V2 Str Vey: C015/84	
-121.9466380000		
A009/228 SINGLE WOOD POLE	//Completed/no problems	Total # of Attachments: 1
40677748	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	2101 0010130 1
	[]not inspctd this patrol	,
	Notes: '02 Survey: C015765	
38.304493000000		
-121.9470760000		y .
A009/229 SINGLE WOOD POLE		Total # of Attachments: 1
40650171	[]completed/new finding(s)	
TRI DIN ARM	[]pre-existing cond chked	
T-1(416)	[]not inspctd this patrol	
•	Notes: '02 Survey: C015766	
38.303772000000		
-121.9474020000		
A009/230 SINGLE WOOD POLE		Total # of Attachments: 1
40768136	completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	VR Wall Rails
	[]not inspetd this patrol	X Broke BOND
39.30319400000	Notes: '02 Survey: C015767	•
-121.9478390000		
A009/231 SINGLE WOOD POLE SW 19	Second of adding	
	l'	Total # of Attachments:
FIELD SWITCH STRUCTURE	[]completed/new finding(s)	
Diller Birocibre 30	[]pre-existing cond chked []not inspetd this patrol	
	Notes:	
38.302515000000	1.000	
-121.9481680000	İ	
	<u></u>	

Inspector Name : COPER Date Inspected : ___

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #	
Equip #		Attachment Type/Owner Listed	
Framing Config		,	
Access:			Į.
HOST Tech ID/Equip #:	Notes	<u></u>	
Lat:			
Long:			
A009/232 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1	
40817744	[]completed/new finding(s		3-
ANGLE 0-30 DEGREES	[] pre-existing cond chked		
3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	[] not inspetd this patrol		
1	Notes: '02 Survey: C01576		_
38.301950000000	Modes: No Survey: CO15/8		
-121.9484710000			ł
A009/233 SINGLE WOOD POLE	completed/no problems		
40825113		Total # of Attachments:	
TRI POST	[]completed/new finding(s		
	[]pre-existing cond chked	â	1 /
HEAVY EQP (CRANES, TRACTOR)	[]not inspctd this patrol		i i
20 20101700000	Notes:		Y
38.301917000000			'
-121.9484340000			
A03/079 SINGLE WOOD POLE		Total # of Attachments: 1	3-
40751998	[]completed/new finding(s)	DIST-0310456 1	اح ا
TRI PIN ARM DEAD END	[]pre-existing cond chked		
	[]not inspctd this patrol		
	Notes: '02 Survey: C015615		
38.385291000000	1		1
-121.8782050000			
A03/080 SINGLE WOOD POLE SW 39	completed/no problems	Total # of Attachments: 1	
40767446	[]completed/new finding(s)	DIST-0310456 1	
TRI POST VALS	[]pre-existing cond chked		1
V ACC.	[]not inspetd this patrol		
	Notes: '02 Survey: C015617		
38.384837000000	FIELD SW STRUCTURE.	NO NEED FOR INDIVIDUAL POLE RECORD.	
-121.8786540000	DELETED 5/7/02. S.	WEEKS 720-7105	ì
A03/081 SINGLE WOOD POLE	t completed/no problems	Total # of Attachments: 1	
40810282	[]completed/new finding(s)		
2 HORIZONTAL POST DELTA	[]pre-existing cond chked		
	[]not inspetd this patrol		
	Notes: '02 Survey: C015618	<u> </u>	
38.384326000000	•		
-121.8791180000			
A03/082 SINGLE WOOD POLE	t completed/no problems	Total # of Attachments: 1	
40823422	[]completed/new finding(s)		1
348DE	[]pre-existing cond chked	2551 0320430 1	
2/28	[]not inspetd this patrol		
<i>⊃</i> *	Notes: '02 Survey: C015619		
38.383745000000	Loces. by barvey, correct		
-121.8796190000	,		1
A03/083 SINGLE WOOD POLE	completed/no problems	Install # of 2th observed	
40862288	[]completed/new finding(s)	Total # of Attachments: 1	
TRIANGLE POST 70		DIST-0310456 1	
IRIANGIE FOSI 70	[]pre-existing cond chked		
	[]not inspetd this patrol		
38.383115000000	Notes: '02 Survey: C015620		
			1
-121.8801650000	L		
A03/084 SINGLE WOOD POLE	Ascompleted/no problems	Total # of Attachments: 1	
40868329	[]completed/new finding(s)	DIST-0310456 1	1
TRI POST (C)	[]pre-existing cond chked		ı
`	[]not inspctd this patrol	y .	1
	Notes: '02 Survey: C015621	14.4.	
88.382529000000 -121.8807110000		Pole HAS "C" TIMES	

Page 41

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Inspector Name : Cooper

Date Inspected : _

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	210000	
Long:		
A03/085 SINGLE WOOD POLE		
40590227		Total # of Attachments: 1
	[]completed/new finding(s)	
TRI FOST (C)	[]pre-existing cond chked	
	[]not inspctd this patrol	
38.381932000000	Notes: '02 Survey: C015622	
-121.8812190000		
A03/086 SINGLE WOOD POLE 40599334	completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
T-1(c)	[]not inspetd this patrol	
`	Notes: '02 Survey: C015623	
38.381322000000		?
-121.8817660000		
A03/087 SINGLE WOOD POLE	thrompleted/no problems	Total # of Attachments: 1
40695393	[]completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
۲-۱(۰)	[]not inspetd this patrol	
<u> </u>	Notes: '02 Survey: C015624	
38.380726000000		
-121.8822920000		
A03/088 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40657524	[]completed/new finding(s)	
TRI PIN ARM	pre-existing cond chked	* Flasher Treat
	[]not inspctd this patrol	* Floshero INSUL > 19K
	Notes: '02 Survey: C015625	DETAIL COND TO
38.380275000000		
-121.8827040000		
A03/089 SINGLE WOOD POLE	Jcompleted/no problems	Total # of Attachments: 1
40768101	[]completed/new finding(s)	DIST-0310456 1
THE POST (-1(°)	[]pre-existing cond chked	
	[]not inspetd this patrol	1
	Notes: '02 Survey: C015626	
38.380093000000	_	1
-121.8828590000		
A03/090 SINGLE WOOD POLE	//completed/no problems	Total # of Attachments: 1
40759645	[]completed/new finding(s)	
TRIMBLE DOST 70	[]pre-existing cond chked	
TRIANGLE DOST 70	[]not inspctd this patrol	
	Notes: '02 Survey: C015627	
38.379534000000	1	İ
-121.8833290000	1 .	
A03/091 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40825107	[]completed/new finding(s)	DIST-0310456 1
TRI-FOST ((C)	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015628	
38.37896900000		
-121.8838320000		· I
A03/092 SINGLE WOOD POLE		Total # of Attachments: 1
40816617	[]completed/new finding(s)	
TRIANGLE POST 70 (()	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015629	
38.378358000000		
-121.8843540000	1	
	<u></u>	

Inspector Name : Cooper Date Inspected : 3-19-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

December 1		
Desc of Tech ID	Inspection Result	Attachments #
Equip # Framing Config		Attachment Type/Owner Listed
Access:	34-4	
HOST Tech ID/Equip #:	Notes	
Lat:	3	
Long:		
A03/093 SINGLE WOOD POLE	Teompleted/no problems	Total # of Attachments: 1
40875409	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
22 255522222	Notes: '02 Survey: C015630	
38.377769000000		
-121.8849050000		
A03/094 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40868331 TRIANGLE POST 70	[]completed/new finding(s)	DIST-0310456 1
July 07	[]pre-existing cond chked	
1 700	[]not inspetd this patrol	
30 3223 0000000	Notes: '02 Survey: C015631	
38.377182000000	1 - 12/10 LL.	s "cifeuss
-121.8854750000	C TOLE TTAS	And the second of the second o
A03/095 SINGLE WOOD POLE		Total # of Attachments: 1
40612572	[]completed/new finding(s)	
	[]pre-existing cond chked	
· ·	[]not inspctd this patrol	
30 3865830000	Notes: '02 Survey: C015632	
38.376583000000 -121.8859140000		
A03/096 SINGLE WOOD POLE	1) 2 () ?	
40592609	[]completed/no problems	Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s)	
IRI PIN ARM	pre-existing cond chked [] not inspctd this patrol	XAIM_Some ROC
	Notes: '02 Survey: C015633	Lynn - Down Look
38.376016000000	Motes: '02 Survey: C015633	
-121.8864740000		
A03/097 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40695318	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
	[] not inspetd this patrol	
•	Notes: '02 Survey: C015634	
38.37540200000	Model. Wa Bullyey, Collabat	
-121.887000000		
A03/098 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
-		
40665439		
	[]completed/new finding(s)	
40665439 3 HORIZONTAL POST DELTA	[]completed/new finding(s) []pre-existing cond chked	
	[]completed/new finding(s)	DIST-0310456 1
	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	DIST-0310456 1
3 HORIZONTAL POST DELTA	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	DIST-0310456 1
3 HORIZONTAL POST DELTA	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	DIST-0310456 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635	DIST-0310456 1 Total # of Attachments: 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635	DIST-0310456 1 Total # of Attachments: 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s)	DIST-0310456 1 Total # of Attachments: 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897	[]completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems []completed/new finding(s) []pre-existing cond chked []not inspctd this patrol Notes: '02 Survey: C015636	Total # of Attachments: 1 DIST-0310456 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897 TRI POST	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897 TRI POST 38.374187000000 -121.8881150000 A03/100 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015636	DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897 TRI POST 38.374187000000 -121.8881150000 A03/100 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015636	Total # of Attachments: 1 DIST-0310456 1. Total # of Attachments: 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897 TRI POST 38.374187000000 -121.8881150000 A03/100 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspetd this patrol Notes: '02 Survey: C015636 Completed/no problems [] completed/new finding(s)	Total # of Attachments: 1 DIST-0310456 1. Total # of Attachments: 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897 TRI POST 38.374187000000 -121.8881150000 A03/100 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015636 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897 TRI POST 38.374187000000 -121.8881150000 A03/100 SINGLE WOOD POLE	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015636 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1
38.374789000000 -121.8875670000 A03/099 SINGLE WOOD POLE 40759897 TRI POST 38.374187000000 -121.8881150000 A03/100 SINGLE WOOD POLE 40759647 TRI PIN ARM	[] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015635 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol Notes: '02 Survey: C015636 Completed/no problems [] completed/new finding(s) [] pre-existing cond chked [] not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Total # of Attachments: 1 DIST-0310456 1

Inspector Name : _ Date Inspected : 3-14-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config	1	Introdemient Type/Owner Elsted
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	1.0000	
Long:	1	
A04/101 SINGLE WOOD POLE	1 1 1 1 1 1	
40825109	completed/no problems	Total # of Attachments: 1
	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015638	
38.373025000000		
-121.8891290000		
104/102 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0823458	[]completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015639	
8.372440000000		
121.8896660000		
04/103 SINGLE WOOD POLE	completed/no problems	Total # of Tune!
0875411 /	l completed/no proprems	Total # of Attachments: 1
RI PIN ARM	[]completed/new finding(s)	DISI-0310456 I
AI FIN ARM	[]pre-existing cond chked	,
	[]not inspetd this patrol	
	Notes: '02 Survey: C015640	
8.371860000000		
121.8901890000		
04/104 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
0874375	[]completed/new finding(s)	DIST-0310456 1
ri dost	[]pre-existing cond chked	
116	[]not inspctd this patrol	
~ (Notes: '02 Survey: C015641	
8.371221000000		
121.8907400000		
04/105 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
0612520	Completed/new finding(s)	
RIANGLE POST 78	[]pre-existing cond chked	D721-0370420 T
	[]not inspetd this patrol	
14 (n/c)		To ke N/c Insulation / Middle phase
8.370594000000	Notes: '02 Survey: C015642	
121.8912740000		
04/106 SINGLE WOOD POLE		Total # of Attachments: 1
0592611	[]completed/new finding(s)	DIST-0310456 1
RI PIN ARM	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015643	
3.370064000000	_	
.21.8917380000		
4/107 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
695323	[]completed/new finding(s)	· · · · · · · · · · · · · · · · · · ·
1-20-1 T-1(C)	[]pre-existing cond chked	······································
((<)	[]not inspetd this patrol	
	Notes: '02 Survey: C015644	
.369446000000	2 Bulvey: C015644	
21.8922980000	1	
4/108 SINGLE WOOD POLE	-	Total # of Attachments: 1
657526	[]completed/new finding(s)	DIST-0310456 1
I POST T-((c)	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015645	
.368867000000	I	
150000700000		

Inspector Name : Date Inspected:

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inconception Possella	24
Equip #	Inspection Result	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		•
	89 - L	<u> </u>
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A04/109 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40768103	[]completed/new finding(s)	DIST-0310456 1
TRI POST TILO	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015646	
38.368281000000		
-121.8933380000	<u>بر</u>	
A04/110 SINGLE WOOD POLE	//completed/no problems	Total # of Attachments: 1
40759649	[]completed/new finding(s)	DIST-0310456 1
TRIANGLE POST 70	[]pre-existing cond chked	
7(2003	[]not inspctd this patrol	*
	Notes: '02 Survey: C015647	
38.367661000000]	
-121.8938870000		
A04/111 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40817732	completed/new finding(s)	
TRIANGLE POST 70	i]pre-existing cond chked	
l	[] not inspetd this patrol	WITH V as Des
	Notes: '02 Survey: C015648	TA GROVED WIN IDIN- KOKRAM
38.367083000000	2 Survey: C015648	* Flacher King Pin-ROFRAME T-1 (NC)
-121.8944160000		\—\(\(\frac{1}{2}\)
A04/112 SINGLE WOOD POLE	[] completed/no problems	
40823424		Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
IRI PIN ARM	[]pre-existing cond chked	u u
,	[]not inspctd this patrol	
38 36633999999	Notes: 3640 MARICOPA RD	
38.366328000000		
-121.8950500000		
A04/113 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40868992	[]completed/new finding(s)	DIST-0310456 1
TRE POST	[]pre-existing cond chked	
, , ,	[]not inspetd this patrol	
	Notes: '02 Survey: C015650	
38.365912000000		Ì
-121.8955000000		
A04/114 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40868333	[]completed/new finding(s)	DIST-0310456 1
3 HORIZONTAL POST DELTA	[]pre-existing cond chked	
34PD (°)	[]not inspctd this patrol	
300 C	Notes: '02 Survey: C015651	
38.365337000000		
-121.8959450000		
A04/115 SINGLE WOOD POLE	Feompleted/no problems	Total # of Attachments: 1
40612523	[]completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015652	
38.364708000000		
-121.8964830000		
A04/116 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 2
40599374		DIST-0310456 1; FIBR-UNKNOWN 1
TRI PIN ARM	[]pre-existing cond chked	DIBI-0310430 T; LIRK-ONKNOMN I
	[]not inspetd this patrol	
	Notes: '02 Survey: C015653	
	Mores: .oz satrek: CO19693	
38.364465000000		
38.364465000000 -121.8967430000		

Inspector Name : _____ Date Inspected : 3

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Medium Impact

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Inspection Result	Attachment Type/Owner Listed
Framing Config		Accacimient lybe/Owner misced
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Notes	
Long:	ا .	
A04/117 SINGLE WOOD POLE	[completed/no problems	Total # of Attachments: 1
40695410	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015654	
38.364083000000		
-121.8970710000		
A04/118 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40657528	[completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspctd this patrol	
= 12 2 12 22 22	Notes: '02 Survey: C015655	
38.363515000000		1
-121.8975790000	4.2	
A04/119 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40768132	[]completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015656	
38.363004000000		
-121.8980020000		
A04/120 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40759651	[]completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015657	
38.362508000000	_	
-121.8984030000		
A04/121 SINGLE WOOD POLE]completed/no problems	Total # of Attachments: 1
40825111	[completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspetd this patrol	
	Notes: '02 Survey: C015658	
38.361743000000	_	
-121.8990590000		
A05/122 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40823460	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	·
	[]not inspetd this patrol	
	Notes: '02 Survey: C015659	
38.361137000000		
-121.8996910000	1. 7	'
A05/123 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40875413	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	Table Tabl
(AMARICAN)	[]not inspctd this patrol	
	Notes: '02 Survey: C015660	
38.360563000000		
-121.9002070000		
A05/124 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40868335	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
	[] not inspetd this patrol	
	Notes: '02 Survey: C015661	
38.35996500000	1.5005. 02 Bulvey: C015661	
-121.9007350000		

Inspector Name : _ Date Inspected : _

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	
Equip #	inspection Result	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		
	37- L	
HOST Tech ID/Equip #:	Notes	,
Lat:		
Long:		
A05/125 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40612526	[]completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015662	
38.359377000000		
-121.9012600000		
A05/126 SINGLE WOOD POLE		Total # of Attachments: 1
40592612	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
1	[]not inspctd this patrol	
1	Notes: '02 Survey: C015663	
38.359019000000		` !
-121.9015620000		· ·
A05/127 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 1
40677727	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
100	Notes: '02 Survey: C015664	<u> </u>
38.358750000000		
-121.9018000000		
A05/128 SINGLE WOOD POLE		Total # of Attachments: 1
40599336	[]completed/new finding(s)	DIST 0210456 1
TRI POST	[]pre-existing cond chked	D131-0310436 1
	[] not inspetd this patrol	
	Notes: '02 Survey: C015665	
38.358168000000	Moces. 02 Survey: Corsess	
-121.9023190000		
A05/129 SINGLE WOOD POLE	Leompleted/no problems	martin III of the control of the con
40695398	(completed/new finding(s)	Total # of Attachments: 1
TRIANGLE POST 70	[]pre-existing cond chked	D181-0310456 1
WILLIAM TODI TO	[] not inspetd this patrol	
38.357614000000	Notes: '02 Survey: C015666	
-121.9028010000		
A05/130 SINGLE WOOD POLE		
AUS/13U SINGLE WOOD POLE . 40657530		Total # of Attachments: 1
	[completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspetd this patrol.	
20. 25522500000	Notes: '02 Survey: C015667	
38.356986000000	/	1
-121.9033290000		
A05/131 SINGLE WOOD POLE		Total # of Attachments: 1
40759899	[\completed/new finding(s)	DIST-0310456 1
TRI POST	[]pre-existing cond chked	
	[]not inspctd this patrol	
77. 7564959999	Notes: '02 Survey: C015668	
38.356406000000	1 .	
-121.9038340000		
A05/132 SINGLE WOOD POLE		Total # of Attachments: 1
40767449	[]completed/new finding(s)	DIST-0310456 1
3 HORIZONTAL POST DELTA	[]pre-existing cond chked	
MEDIUM EQP(AERIAL LIFT;LINE TR	[]not inspctd this patrol	<u>, </u>
	Notes: '02 Survey: C015669	
38.355763000000		
-121.9043660000		

Inspector Name : Coopen Date Inspected : 3-28-12

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Transaction Boards	
Equip #	Inspection Result	Attachments #
Framing Config		Attachment Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:	Roces	
Long:	/	
A05/133 SINGLE WOOD POLE	icompleted/no problems	Total # of Attachments: 1
40817734	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	D131-0310456 1
	[] not inspetd this patrol	
	Notes: '02 Survey: C015670	
38.355128000000]	
-121.9049550000		
A05/134 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40823426	[]	mmm
TRI PIN ARM DEAD END	pre-existing cond chked	VO . 1
	[]not inspetd this patrol	DIEPACE (A) Archors & Cappectans
1	Notes: '02 Survey: C015671	10.4
38.354627000000		BREPACE (2) Archors & Connections Myn
-121.9054740000		
A05/135 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40868994	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
1	[]not inspctd this patrol	
İ	Notes: '02 Survey: C015672	
38.354589000000		
-121.9055890000		
A05/136 SINGLE WOOD POLE 40874343	completed/no problems	Total # of Attachments:
TRI PIN ARM	[]completed/new finding(s)	
IRI PIN ARM	[]pre-existing cond chked	
	[] not inspetd this patrol	
38.354556000000	Notes: '02 Survey: C015673	
-121.9061020000		
A05/137 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40612517	[] completed/new finding(s)	
DOUBLE VERTICAL	Dre-existing cond chked	(0 mous - 14n
,	[]not inspetd this patrol	8INSULATORS * Anchors
	Notes: '02 Survey: C015674	DIPOUNT COLO & ADOUGHS
38.354506000000		
-121.9063080000		1
A05/138 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40592614	[]completed/new finding(s)	
TRI POST	Libre-existing cond chked	
HEAVY EQP (CRANES, TRACTOR)	[]not inspetd this patrol	* LEANING POLE - 24KS
	Notes: '02 Survey: C015675	•
38.353994000000	MONITOR LEANING POLE	
-121.9067700000		
A05/139 SINGLE WOOD POLE		Total # of Attachments:
40695327	[]completed/new finding(s)	
TRI POST	[]pre-existing cond chked	
]	[] not inspetd this patrol	
38.353325000000	Notes: '02 Survey: C015676	
-121.9073050000		
1	completed/no problems	Total # of Attachments:
40665440	[]completed/new finding(s)	τουαι π οι Attachments:
TRI PIN	[]pre-existing cond chked	7
_ ,	[]not inspetd this patrol	
~	Notes: '02 Survey: C015677	
38.353070000000		
-121.9075770000		

Inspector Name : _ Date Inspected:

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Inspection Result	Attachment Type/Owner Listed
Framing Config		Accadement Type/Owner Listed
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A05/141 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments:
40759901	completed/new finding(s)	
TRI PIN	[]pre-existing cond chked	
	[]not inspetd this patrol	A Etrane T-1
	Notes: '02 Survey: C015678	
38.352502000000		
-121.9080900000		
A05/142 SINGLE WOOD POLE	completed/no problems	Total # of Attachments:
40759653	[]completed/new finding(s)	
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspctd this patrol	
22 25101000000	Notes: '02 Survey: C015679	
38.351919000000 -121.9085890000		
A05/143 SINGLE WOOD POLE	Completed/no problems	Implication of the Control of the Co
40823463		Total # of Attachments: 1
	[]completed/new finding(s) []pre-existing cond chked	DT21-02T0420 T
TRI POST T-1(0)	[] not inspetd this patrol	
l	Notes: '02 Survey: C015680	
38.351308000000	notes. 02 Salvey: Colseso	
-121.9091110000		
A05/144 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments 2
40868996	[]completed/new finding(s)	
TRI PIN ARM	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015681	
38.350839000000		
-121.9096410000		
A06/145 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 2
40874345	[]completed/new finding(s)	DIST-0310456 2
TRI POST T-YO	[]pre-existing cond chked	
' `	[]not inspctd this patrol	
38.35049200000	Notes: '02 Survey: C015682	
-121.9099580000		
A06/146 SINGLE WOOD POLE	Completed/no problems	Total # of Attachments: 1
40612564	[]completed/new finding(s)	
TRIANGLE DOCT TO	[]pre-existing cond chked	2707 02T0#30 7
1	[]not inspctd this patrol	
``	Notes: '02 Survey: C015683	
38.349922000000		
-121.9103900000		Post's Britis Nor Jung
A06/147 SINGLE WOOD POLE		Total # of Attachments: 2
40599385		DIST-0310456 1; STLT-UNKNOWN 1
TRIANGLE POST 70	[]pre-existing cond chked	
T4(e)	[]not inspetd this patrol	
· -	Notes: '02 Survey: C015684	STREET LIGHT
38.349676000000 -121.9106450000		
A06/148 SINGLE WOOD POLE	[Vecompleted/no problems	Total # of Attachments 1
40677731		Total # of Attachments: 1
TRIANGLE FOST 70	[]pre-existing cond chked	11.01.402T0.430 ↑
CONTRACTOR CONTRACTOR	[]not inspetd this patrol	
T-1 (NC)	Notes: '02 Survey: C015685	
38.349469000000		
-121.9107970000		

Inspector Name : Coopel Date Inspected : 3 -23 -

Funct Loc : ETL.6730.POLE.WOOD

60066 DIXON-VACA #1+-WOOD POLE

: 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		The same of the sa
Access:		
HOST Tech ID/Equip #:	Notes	<u></u>
Lat:		
Long:		
A06/149 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 2
406654,43	[]completed/new finding(s)	DIST-0310456 1; STLT-UNKNOWN 1
TRIANGLE POST 70	[]pre-existing cond chked	
	[]not inspctd this patrol	
	Notes: '02 Survey: C015686	STREET LIGHT
38.349187000000		1
-121.9110640000	<u> </u>	
A06/150 SINGLE WOOD POLE	recompleted/no problems	Total # of Attachments: 2
41118543 TRIANGLE POST 70	[]completed/new finding(s)	DIST-0310456 1; STLT-UNKNOWN 1
TRIMIGLE POST /U	[]pre-existing cond chked	
	[]not inspctd this patrol	<u> </u>
38.348662000000	Modes: 'U2 Survey: C015687	STREET LIGHT Equip. not in GAD
-121.9115230000		
A06/151 SINGLE WOOD POLE		Mohal H of July 2
40759903	[]completed/no problems	Total # of Attachments: 1
TRI POST		D15T-U310456 1
Thes	[]pre-existing cond chked []not inspctd this patrol	
	Notes: '02 Survey: C015688	
38.348359000000	Notes: '02 Survey: C015688	
-121.9117490000		
A06/152 SINGLE WOOD POLE	completed/no problems	Total # of Attachments: 2
40767451	[]completed/new finding(s)	DIST-0310456 1; STLT-UNKNOWN 1
TRIANGLE POST 70	[]pre-existing cond chked	DISI-0310436 I; SIDI-0NKNOWN I
101	[]not inspctd this patrol	
	Notes: '02 Survey: C015689	STREET LIGHT
38.348062000000		
-121.9120160000		
A06/153 SINGLE WOOD POLE	[]completed/no problems	Total # of Attachments: 1
40817736	[]completed/new finding(s)	DIST-0310456 1
FLAT PIN ARM	[]pre-existing cond chked	
1 1/A	[]not inspctd this patrol	
	Notes: '02 Survey: C015690	
38.347757000000		
-121.9122460000		
A06/154 SINGLE WOOD POLE		Total # of Attachments: 1
40816619	[]completed/new finding(s)	DIST-0310456 1
TRI PIN ARM	[]pre-existing cond chked	i
	[]not inspetd this patrol	
	Notes: '02 Survey: C015691	
38.347488000000	A	MIS WEATHERED
-121.9125080000 A06/155 SINGLE WOOD POLE		
1 (2)		Total # of Attachments: 1
TRI PIN ARM	[]completed/new finding(s)	DIST-0310456 1
	[]pre-existing cond chked	
	[]not inspctd this patrol Notes: '02 Survey: C015692	
38.346958000000	Notes: 02 Survey: C015692	
-121.9130400000		
B10/238 SINGLE WOOD POLE		Total # of Attachments:
	[]completed/new finding(s)	TOTAL # OI ACCACHMENTS:
I	[]pre-existing cond chked	
	[]not inspetd this patrol	
l	Notes:	
38.477069000000		
-121.7974770000		

1

30/12513	E1E.6730 03/31/2012 05/20/2002 30/12513	03/31/2012	E1L.6/30	40000321	THE CONTRACTOR STEE		-
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	E1L.6730	40601219	DOON SO SINGLE WOOD PO	05/20/2002 DIXON VACA #1 6/153 REPL POLE	100485505
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40599333	SINGLE WOOD	04/01/2008 DIXON-VACA #1 6/151	103735780
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730		SINGLE WOOD	04/01/2008 DIXON-VACA #1 6/150 BRIDGE	_
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40657515	SINGLE WOOD	04/01/2008 DIXON-VACA #1 6/149 BRIDGE	103/35///
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730		WOOD	04/01/2008 DIXON-VACA #1 6/148 BRIDGE	103/35//6
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730		006/147 SINGLE WOOD POLE	-	103/35/75
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40817728	SINGLE WOOD	04/01/2008 DIXON-VACA #1 6/146 BRIDGE	103/35//4
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40823420	MOOD	04/01/2008 DIXON-VACA #1 6/145 BRIDGE	103/35//3
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730			04/01/200	1635772
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730		006/143 SINGLE WOOD POLE	04/01/200	
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40695385	006/142 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 6/142 BRIDGE	103/35//0
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730			04/01/2008 DIXON-VACA #1 6/141 BRIDGE	103/35/39
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730		006/140 SINGLE WOOD POLE	04/01/200	103/35/38
	04/14/2008	ETL.6730 12/31/2015 04/14/2008	ETL.6730	40618239	005/127 NON-CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 5/127	103/3103/
u	04/14/2008	ETL.6730 12/31/2015 04/14/2008	ETL.6730	40788977	005/123 NON-CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 5/123 IDENTIFY	103/31036
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40817730	004/112 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 4/112	103/35669
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40816613	004/111 SINGLE WOOD POLE	04/01/2008 DIXON-VACA	103/35668
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40875446	004/110 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 4/110 BRIDGE	103735667
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40862038	004/109 SINGLE WOOD POLE	04/01/2008 DIXON-VACA	103/35666
30870158	03/15/2010/30870158	ETL.6730 09/31/2012	ETL.6730	40759641	NEED TO DO -	03/15/2010 DIXON-VACA #1 4/103 RPL AND	104707319
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40825100	004/102 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1	103/35660
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40823451	004/101 SINGLE WOOD POLE	04/01/2008 DIXON-VACA	103/355/9
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.6730			04/01/2008 DIXON-VACA #1 4/100 BRIDGE	103735578
	04/01/2008	ETL.6730 12/31/2015	ETL.6730	_	004/099 SINGLE WOOD POLE	04/01/2008 DIXON-VACA	103735577
			ETL.6730	40626015	ERAI	04/14/2008 DIXON-VACA #1 3/90 IDENTIFY SPLICES	16~,31035
41630063	12/28/2011 4		ETL.6730	40589592	NEED TO DO/ REPLACESWOLE SW 59	12/28/2011 DIXON VACA #1 2/77 SW 59 CLEAR VEG*	1r 51093
30629966	01/28/2008 30629966	_	ETL.6730	40612561	[YEARL - Pole Sport -	01/28/2008	102895595
	04/14/2008	\neg	ETL.6730	40898765	002/075 CERAMIC INSULATOR	04/14/2008	103731034
	03/21/2011	-1	ETL.6730	40756195	S - 902/054 SINCLE WOOD POLE	03/21/2011	105251145
30768564	03/17/2009 30768564	ETL.6730 03/31/2012	ETL.6730	40865460		03/1 //2009	103/49105
	03/21/2011	00	ETL.6730	40665433		03/21/2011 DIXON-VACA #1 1/41 RPL XARM (105251140
	10/06/2011		ETL.6730	40865996	FOUND COMPLETED POLE	10/06/2011	105495624
	03/01/2010	ETL.6730 03/31/2013	ETL.6730	40756286	ı	03/01/2010 DIXON-VACA #1 0	104/0/18/
	03/01/2010	11/30/2015	ETL.6730	40599369	000/001 SINGLE WOOD POLE	03/01/2010	104707180
Order				Equipment	Description	Notif.date	Notification
	Reference	Required F	Function				

		1				
	04/14/2008	ETL.6730 12/31/2015 0	ETL.6730	40893504	AUU9/224 CERAMIC INSULATOR	H
	4/14/2008	12/31/2015 04/14/2008	ETL.6730	40845658	ULATOR	04/14/2008
	4/14/2008	ETL.6730 12/31/2015 04/14/2008	ETL.6730	40799627	CINSULATOR	04/14/2008
	4/14/2008	ETL.6730 12/31/2015 04/14/2008	ETL.6730	ļ -		04/14/2008
	4/14/2008	ETL.6730 12/31/2015 04/14/2008	ETL.6730	ļ.,	CERAMIC INSULATOR	04/14/2008
	4/14/2008	ETL.6730 12/31/2015 04/14/2008	ETL.6730	上	INCOLATOR	\dashv
	4/14/2008	ETL.6730 12/31/2015 04/14/2008	ETL.6730	上	CERAWIC INSULATOR	-+
	04/14/2008	ETL.6730 12/31/2015 0	ETL.6730		CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 A9/213 IDENTIFY SELICE
	04/14/2008		ETL.6730		NON-CERAMIC INSULATOR	
	04/14/2008		ETL.6730		ACCOZO CEXAMIC INSULATOR	3732216
	04/14/2008		ETL.6730		CERAMIC INSULATOR	-
	04/14/2008	$\overline{}$	ETL.6730	L.	CERAMIC INSULATOR	-
	04/14/2008	ETL.6730 12/31/2015 0	ETL.6730	L	ULATOR	┯╁
	04/14/2008		ETL.6730	<u> </u>	ULATOR	04/14/2008
	04/14/2008	12/31/2015		40/88993		04/14/2008 DIXON-VACA #1 A8/200 IDENTIFY SDLICE
	04/14/2008	12/31/2015	TL.6730	40790006	A008/190 CERAMIC INSULATOR	04/14/2008
1	04/14/2008	12/31/2015	IL.6/30	40696//3	ADDRIAND DEDAMIC INSULATOR	04/14/2008
	04/01/2008	12/31/2015	E1L.6730		ADDRIAG CERAMIC INICID POLE	04/14/2008
)4/14/2008	12/31/2015 04/14/2008	E1L.6730			04/01/2008
)4/14/2008	E1L.6/30 12/31/2015 04/14/2008	E1L.6/30	1		
	4/14/2008	E1L.6/30 12/31/2015 04/14/2008	E11.6/30	40901285	A008/192 CERAMIC INSULATOR	04/14/2008
)4/14/2008	E1L.6/30 12/31/2015 04/14/2008	E1L.6/30	40842437		04/14/2008
	04/14/2008	E1L.6/30 12/31/2015 C	E1L.6/30	4009077	CEBAMIC ING	103732154 04/14/2008 DIXON-VACA #1 A7/190 IDENTIFY SPI ICES
)4/14/2008	ET 6730 12/31/2015 04/14/2008	ET 6730	40606774		103732153 04/14/2008 DIXON-VACA #1 A7/186 IDENTIFY SPLICES
	04/14/2008	ETI 6730 12/31/2013 C	ETI 6730	40722228	A007/185 CERAMIC INSIII ATOR	103732151 04/14/2008 DIXON-VACA #1 A7/185 IDENTIFY SPLICES
	0000/14/14/14/14/14/14/14/14/14/14/14/14/14/	10/21/0015	ETI 6730	40635034	A007/183 CERAMIC INSULATOR	103732150 04/14/2008 DIXON-VACA #1 A7/183 IDENTIFY SPLICES
	04/14/2008	[-	FTI 6730	40898775	A007/182 CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 A7/182 IDENTIFY
	04/14/2008		FTI 6730	40893500	A007/181 CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 A7/181 IDENTIFY
	04/4//2008	Т	FTI 6730	40854379	A007/179 CERAMIC INSULATOR	4-
	04/14/2008	12/31/2015	ETL.6730	40798240	A007/178 CERAMIC INSULATOR	╁
	03/25/2010	03/31/2012	ETL.6730	40657534	E A007/176 SINGLE WOOD POLE	╁
	03/25/2010	03/31/2012		40695335	E A007/175 SINGLE WOOD POLE	+
	04/14/2008	12/31/2015	ETL.6730	40732143	AUU//1/5 CERAMIC INSULATOR	┰
	04/14/2008	12/31/2015	ETL.6730	40618252	A00//1/4 CERAMIC INSULATOR	04/14/2008
	04/01/2008	12/31/2015	ETL.6730	40816623	AUU//1/1 SINGLE WOOD POLE	04/14/2008
	04/14/2008	12/31/2015	ETL.6730	40842435	A007/171 CERAMIC INSULATOR	04/01/2008
	04/14/2008	12/31/2015	ETL.6730	40837109	AUU6/1/U CERAMIC INSULATOR	732122 04/14/2008
j	04/14/2008	12/31/2015	ETL.6730	40799611	A006/168 CERAMIC INSULATOR	04/14/2008
						103732019 04/14/2008 DIXON WACA #4 ASMSS IDENTIFY OF LOED

2008	04/14/2008	ETL.6730 12/31/2015	ETL.6730	40696820	A006/167 CERAMIC INSULATOR	018 04/14/2008 DIXON-VACA #1 A6/167 IDENTIFY SPLICES	103732018
2008		12/31/2015	ETL.6730		A006/166 CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 A6/166	103732017
2010	03/22/2010	ETL.6730 03/31/2012	ETL.6730	40816621	D POLE	03/22/2010 DIXON-VACA #1 A6/161 INSTALL S	104706908
2010	03/22/2010	ETL.6730 11/30/2015	ETL.6730	40816621	16.5	185 03/22/2010 DIXON-VACA #1 A6/161 RPL CONNECTORS	104707185
2010	03/22/2010	ETL.6730 03/31/201	ETL.6730	40810284	2 Years	03/22/2010 DIXON-VACA #1 A6/160	104706907
2010	03/22/2010	ETL.6730 11/30/2015	ETL.6730	40810284	Thems an OD POLE	184 03/22/2010 DIXON-VACA #1 A6/160 RPL CONNECTORS	104707184
2008	04/01/2008	ETL.6730 12/31/2015	ETL.6730	40874401	, 010/236 SINGLE WOOD POLE	849 04/01/2008 DIXON-VACA #1 10/236 BRIDGE BONDING .	103735849
2008	04/14/2008	ETL.6730 12/31/2015	ETL.6730		ERAMIC INSU	590 04/14/2008 DIXON-VACA #1 10/236 IDENTIFY SPLICES	103731590
2010	03/29/2	ETL.6730 03/31/2014 03/29/2010	ETL.6730		2 Yearn DD POLE	314 03/29/2010 DIXON-VACA #1 10/234 RPL INSULATORS	104707314
2008	04/01/2008	ETL.6730 12/31/2015	ETL.6730		010/233 SINGLE WOOD POLE	848 04/01/2008 DIXON-VACA #1 10/233 BRIDGE BONDING	100/35848
2008	04/14/2008	ETL.6730 12/31/2015	ETL.6730	40618231	010/233 CERAMIC INSULATOR	559 04/14/2008 DIXON-VACA #1 10/233 IDENTIFY SPLICES	1 731559
2008	04/01/2008	ETL.6730 12/31/2015	ETL.6730	40677715	MOOD	847 04/01/2008 DIXON-VACA #1 10/232 BRIDGE BONDING	103735847
2008	04/01/2008	ETL.6730 12/31/2015	ETL.6730		010/231 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1	103735846
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40759881	SINGLE WOOD	845 04/01/2008 DIXON-VACA #1 10/230 BRIDGE BONDING	103735845
03/29/2010 30787048	03/29/2	ETL.6730 03/31/2018	ETL.6730 (_	I YEAR JD POLE	03/29/2010 DIXON VACA #1	104714096
2008	04/01/2008	ETL.6730 12/31/2015	ETL.6730		010/229 SINGLE WOOD POLE	844 04/01/2008 DIXON-VACA #1 10/229 BRIDGE BONDING	103735844
2008	04/14/2008	ETL.6730 12/31/2015	ETL.6730	40791342	010/229 CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 10/229 IDENTIFY SPLICES	103731558
2010	03/29/2	ETL.6730 03/31/2013 03/29/2010	ETL.6730 (40825161	1 Year DD POLE	03/29/2010 DIXON-VACA #1 10/228 RPR LEANING POL	104707188
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40825161	010/228 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 10/228 BRIDGE BONDING	103735843
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40601210	010/224 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 10/224 BRIDGE BONDING	103735842
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730 ·	40657509	010/222 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 10/222 BRIDGE BONDING	103735841
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730		010/221 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 10/221 BRIDGE BONDING	103735840
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730 ·		010/220 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 10/220 BRIDGE BONDING	103735839
2010	03/18/2010	ETL.6730 03/31/2013	ETL.6730 (40759627	I YEAR NOOD POLE	03/18/2010 DIXON-VACA #1 10/220 RPR BOND WIRE	104706902
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730 ·	40816605 I	10/218 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 10/218 BRIDGE BONDING	103735838
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730 ·		019/217 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 10/217 BRIDGE BONDING	100/35837
2008	04/14/2	ETL.6730 12/31/2015 04/14/2008	ETL.6730	\dashv	010/216 CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 10/216 IDENTIFY SPLICES	1 731557
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730		010/214 SINGLE WOOD POLE		103735836
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730	40732210 E	010/213 CERAMIC INSULATOR		103735835
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730	41102751 E	010/212 SINGLE WOOD POLE	834 04/01/2008 DIXON-VACA #1 10/212 BRIDGE BONDING	103735834
2008	04/14/2	ETL.6730 12/31/2015 04/14/2008	ETL.6730 ·	41102750 E	010/212 CERAMIC INSULATOR	04/14/2008 DIXON-VACA #1 10/212 IDENTIFY SPLICES	103731556
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730		009/211 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 9/211 BRIDGE BONDING	103735833
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730		009/210 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 9/210 BRIDGE BONDING	103735832
2010	03/18/2	ETL.6730 03/31/2015 03/18/2010	ETL.6730 (40677719 E	1 YEAR VOOD POLE	03/18/2010 DIXON-VACA #1 9/210 RPL (2) XARMS	104707316
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	TL.6730		009/209 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 9/209 BRIDGE BONDING	103735831
2008	04/14/2	ETL.6730 12/31/2015 04/14/2008	ETL.6730	40789986 E	009/208 CERAMIC INSULATOR	555 04/14/2008 DIXON-VACA #1 9/208 IDENTIFY SPLICES	103731555
2008	04/01/2	ETL.6730 12/31/2015 04/01/2008	ETL.6730 7	40767514 E	009/207 SINGLE WOOD POLE	830 04/01/2008 DIXON-VACA #1 9/207 BRIDGE BONDING	103735830

¥.

	04/01/2008	E1L.6/30 12/31/2015	E1L.6/3	40823488	JOOSIZOS SINGLE WOOD POLE	
	04/14/2008		ETL.6730	40850736	CERAMIC INSU	103/31554 04/14/2008 DIXON-VACA #1 9/205 IDENTIFY SPLICES
	04/01/2008	12/31/2015	ETL.6730	40875471	009/204 SINGLE WOOD POLE	-
	04/01/2008		ETL.6730	40601213	009/202 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 9/202 BRIDGE
0787048	03/18/2010 30787048		ETL.673	40601213	2 YEARS ID POLE	03/18/2010 DIXON VACA #1 9/202 REPI
	04/14/2008	ETL.6730 12/31/2015	ETL.673	40626040		
	04/14/2008	ETL.6730 12/31/2015	ETL.673	40789987	009/198 CERAMIC INSULATOR	┿╌
	04/01/2008	ETL.6730 12/31/2015	ETL.673	40759629		┉
	04/14/2008	ETL.6730 12/31/2015	ETL.673	40788967	CINSU	┢
	04/01/2008	ETL.6730 12/31/2015	ETL.673	40817724	009/196 SINGLE WOOD POLE	04/01/2008 DIXON-VACA #1 9/196 BRIDGE
	04/01/2008	ETL.6730 12/31/2015	ETL.673	40823486	WOOD	04/01/2008
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.673	41374066	009/194 SINGLE WOOD POLE	735823 04/01/2008
	03/08/2010	ETL.6730 11/30/2015 03/08/2010	ETL.673	41195900	PAC TEEL	\vdash
	04/14/2008	TL.6730 12/31/2015 04/14/2008	ETL.673	42572178	009/193 CERAMIC INSULATOR	103731110 04/14/2008 DIXON-VACA #1 9/193 IDENTIFY SPLICES
	04/01/2008	ETL.6730 12/31/2015 04/01/2008	ETL.673	40665509		03735822 04/01/2008 DIXON-VACA #1 8/189 BRIDGE BONDING
-	04/14/2008	ETL.6730 12/31/2015 04/14/2008	ETL.673	40696837	008/189 CERAMIC INSULATOR	03731039 04/14/2008 DIXON-VACA #1 8/189 IDENTIFY SPLICES
	02/15/2012	ETL.6730 02/28/2013 02/15/2012	ETL.673	40767512	HEL POLE	05937448 02/15/2012 DIXON VACA #1 8/187 RPL STRUCTURE V
	04/01/2008	ETL.6730 12/31/2015	ETL.673	40612509	007/176 SINGLE WOOD POLE	03735821 04/01/2008 DIXON-VACA #1 7/176 BRIDGE BONDING
	04/01/2008	ETL.6730 12/31/2015	ETL.673	40891316	007/175 CERAMIC INSULATOR	103735820 04/01/2008 DIXON-VACA #1 7/175 BRIDGE BONDING
	04/01/2008		ETL.673	40816990	007/174 SINGLE WOOD POLE	03735809 04/01/2008 DIXON-VACA #1 7/174 BRIDGE BONDING
	04/01/2008		ETL.673	40868319	007/172 SINGLE WOOD POLE	03735807 04/01/2008 DIXON-VACA #1 7/172 BRIDGE BONDING
	04/01/2008		ETL.673	40592600	007/171 SINGLE WOOD POLE	03735806 04/01/2008 DIXON-VACA #1 7/171 BRIDGE BONDING
	04/01/2008		ETL.673	40695290	007/170 SINGLE WOOD POLE	03735805 04/01/2008 DIXON-VACA #1 7/170 BRIDGE BONDING
	04/01/2008		ETL.673	40657513	NGLE WOOD	03735804 04/01/2008 DIXON-VACA #1 7/169 BRIDGE BONDING
	03/18/2010		ETL.673	40759889	KYEARS OOD POLE	104707313 03/18/2010 DIXON-VACA #1 7/168 RPL INSULATORS /
	04/01/2008		ETL.673	40759889	1007/168 SINGLE WOOD POLE	/35803 04/01/2008 DIXON-VACA #1 7/168 BRIDGE BONDING
	04/01/2008		ETL.673	40825094	007/166 SINGLE WOOD POLE.	10-735801 04/01/2008 DIXON-VACA #1 7/166 BRIDGE BONDING
	04/01/2008	_	ETL.673	40816609	007/165 SINGLE WOOD POLE	103735800 04/01/2008 DIXON-VACA #1 7/165 BRIDGE BONDING
	04/01/2008	12/31/2015	ETL.673	40875434	007/164 SINGLE WOOD POLE	103735789 04/01/2008 DIXON-VACA #1 7/164 BRIDGE BONDING
	04/01/2008		ETL.6730	40874377	007/163 SINGLE WOOD POLE	03735788 04/01/2008 DIXON-VACA #1 7/163 BRIDGE BONDING
	04/01/2008	12/31/2015	ETL.673	40612569		103735787 04/01/2008 DIXON-VACA #1 7/162 BRIDGE BONDING
	04/14/2008	12/31/2015	ETL.6730	40639654	007/162 NON-CERAMIC INSULATOR	103731038 04/14/2008 DIXON-VACA #1 7/162 IDENTIFY SPLICES
	04/01/2008	12/31/2015		40592602	007/161 SINGLE WOOD POLE	103735786 04/01/2008 DIXON-VACA #1 7/161 BRIDGE BONDING
	04/01/2008	12/31/2015	ETL.6730	40695294	007/160 SINGLE WOOD POLE	103735785 04/01/2008 DIXON-VACA #1 7/160 BRIDGE BONDING
	04/01/2008	12/31/2015	ETL.6730	40665488	007/159 SINGLE WOOD POLE	103735784 04/01/2008 DIXON-VACA #1 7/159 BRIDGE BONDING
	04/01/2008	$\overline{}$	ETL.6730	40767442		03735783 04/01/2008 DIXON-VACA #1 7/157 BRIDGE BONDING
	04/01/2008	ETL.6730 12/31/2015	ETL.673	40823418	006/155 SINGLE WOOD POLE	103735782 04/01/2008 DIXON-VACA #1 6/155 BRIDGE BONDING

.

04/14/2008	12/31/2015		04/14/2008 DIXON-VACA #1 A5/132 IDENTIFY SPLICES A05/132 CERAMIC INSULATOR	103731737 04/1
04/14/2008	\neg		04/14/2008 DIXON-VACA #1 A5/130 IDENTIFY SPLICES A05/130 CERAMIC INSULATOR	103731736 04/1
04/14/2008	ETL.6730 12/31/2015 (SPLICE	┼
04/14/2008	_		IDENTIFY SPLICES A05/124 CERAMIC INSU	-
04/14/2008	\neg		A05/123 CERAMIC	103731733 04/1
04/14/2008	12/31/2015		A05/122 CERAMIC INSU	103731732 04/1
04/14/2008	12/31/2015		A04/121 CERAMIC INSU	103731731 04/1
04/14/2008	\neg		A04/119 CERAMIC	╁
04/14/2008	12/31/2015	40687289	DIXON-VACA #1 A4/118 IDENTIFY SPLICES A04/118 CERAMIC INSU	┝┈
04/14/2008			04/14/2008 DIXON-VACA #1 A4/117 IDENTIFY SPLICES A04/117 CERAMIC INSULATOR	
04/14/2008				102731694 04/1
04/14/2008	_	40893492	14/2008 DIXON-VACA #1 A4/113 IDENTIFY SPLICES A04/113 CERAMIC INSULATOR	103731693 04/1
04/14/2008			04/14/2008 DIXON-VACA #1 A4/111 IDENTIFY SPLICES A04/111 NON-CERAMIC INSULATOR	103731692 04/1
04/14/2008	ETL.6730 12/31/2015 C	40799609	04/109 CERAMIC INSU	103731691 04/1
04/14/2008			04/108 CERAMIC INSU	103731690 04/1
04/14/2008		40732137	04/107 CERAMIC INSU	103731659 04/1
04/14/2008			14/2008 DIXON-VACA #1 A4/105 IDENTIFY SPLICES A04/105 NON-CERAMIC INSULATOR	103731658 04/1
04/14/2008			14/2008 DIXON-VACA #1 A4/104 IDENTIFY SPLICES A04/104 CERAMIC INSULATOR	103731657 04/1
04/14/2008			04/103 CERAMIC INSU	103731656 04/1
04/14/2008	ETL.6730 12/31/2015 C		SPLICES A04/101 CERAMIC INSU	103731655 04/1
04/14/2008			03/100 CERAMIC INSU	103731654 04/1
04/14/2008			A03/097 CERAMIC INSU	103731653 04/1
03/09/2010	ETL.6730 03/31/2014 C		LE WOOD	104707317 03/0
04/14/2008	ETL.6730 12/31/2015 C	- 1	04/14/2008 DIXON-VACA #1 A3/96 IDENTIFY SPLICES A03/096 CERAMIC INSULATOR	-
)4/14/2008	ETL.6730 12/31/2015 C		S A03/093 CERAMIC INSU	103731651 04/1
04/14/2008	ETL.6730 12/31/2015 C	40842428	DIXON-VACA #1 A3/92 IDENTIFY SPLICES A03/092 CERAMIC INSU	1, 31650 04/1
04/14/2008	ETL.6730 12/31/2015 C	40788983	S A03/090 CERAMIC INSU	10~731599 04/1
03/09/2010		_	DIXON-VACA #1 A3/88 RPR BOND WIRE	104706905 03/0
03/21/2011	ETL.6730 03/31/2013 0		MEAN	105251143 03/2
)4/14/2008	ETL.6730 12/31/2015 04/14/2008			103731598 04/1
)4/14/2008	ETL.6730 12/31/2015 0		04/14/2008 DIXON-VACA #1 A3/87 IDENTIFY SPLICES A03/087 CERAMIC INSULATOR	103731597 04/1
04/14/2008			04/14/2008 DIXON-VACA #1 A3/85 IDENTIFY SPLICES A03/085 CERAMIC INSULATOR	103731596 04/1
04/14/2008	12/31/2015		DIXON-VACA #1 A3/84 IDENTIFY SPLICES A03/084 CERAMIC	103731594 04/1
04/14/2008	12/31/2015	_	DIXON-VACA #1 A3/83 IDENTIFY SPLICES A03/083 CERAMIC INSU	103731593 04/1
04/14/2008			DIXON-VACA #1 A3/82 IDENTIFY SPLICES A03/082 CERAMIC INSUI	103731592 04/1
04/14/2008	ETL.6730 12/31/2015 0			
)4/14/2008	ETL.6730 12/31/2015 04/14/2008	40898777 I	04/14/2008 DIXON-VACA #1 A9/225 IDENTIFY SPLICES A009/225 CERAMIC INSULATOR	103732257 04/1

			ь.		
30870158	04/14/2008 03/15/2010 03/15/2010 03/15/2010 03/17/2008 03/15/2010 04/14/2008 04/14/2008 04/14/2008 04/14/2008 04/14/2008	ETL.6730 12/31/2015 04/14/2008 ETL.6730 11/30/2015 03/15/2010 ETL.6730 03/31/2015 03/15/2010 30870158 ETL.6730 03/31/2013 03/15/2010 ETL.6730 03/31/2013 03/15/2010 ETL.6730 03/31/2013 03/15/2010 ETL.6730 12/31/2013 03/15/2010 ETL.6730 12/31/2015 04/14/2008 ETL.6730 12/31/2015 04/14/2008 ETL.6730 12/31/2015 04/14/2008 ETL.6730 12/31/2015 04/14/2008 ETL.6730 12/31/2015 04/14/2008	40850672 ET 40823426 ET 40823426 ET 40612517 ET 40612517 ET 40692614 ET 41118542 ET 40790002 ET 40798198 ET 40842430 ET	A05/134 CERAMIC INSULATOR I YEAK POLE I WEAK POLE I MOUS - I YK POLE I MOUS - I YK A06/150 CERAMIC INSULATOR A06/151 CERAMIC INSULATOR A06/152 CERAMIC INSULATOR A06/153 CERAMIC INSULATOR A06/154 CERAMIC INSULATOR	103731738 04/14/2008 DIXON-VACA #1 A5/134 IDENTIFY SPLICES / 104707183 03/15/2010 DIXON-VACA #1 A5/134 RPL CONNECTORS / 104707470 03/15/2010 DIXON-VACA #1 A5/134 RPL (2) ANCHORS / 104707315 03/15/2010 DIXON-VACA #1 A5/137 RPL INSULATORS / 103686440 03/17/2008 DIXON-VACA #1 A5/137 RPL 2 ANCHORS / 104707189 03/15/2010 DIXON-VACA #1 A5/138 RPR LEANING POLE / 103731739 04/14/2008 DIXON-VACA #1 A6/150 IDENTIFY SPLICES / 103731776 04/14/2008 DIXON-VACA #1 A6/151 IDENTIFY SPLICES / 103732015 04/14/2008 DIXON-VACA #1 A6/153 IDENTIFY SPLICES / 103732015 04/14/2008 DIXON-VACA #1 A6/154

